

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 GAEIH2200-00000-0034111145

CON'T

01 REPORT SOURCE L605000366706258180717819

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 7-25-81, following maintenance on clogged motor cooling water line

03 RHR service water pump 2E11-C001A failed to meet acceptance criteria for

04 operability. An LCO was declared per Unit 2 Tech Specs. 3/4.7.1.1

05 action A.1. A similar event was reported by LER 50-366/1980-085. There

06 were no effects upon public health and safety due to this event.

07

09

SYSTEM CODE WA11 CAUSE CODE E12 CAUSE SUBCODE X13 COMPONENT CODE PUMPXX14 COMP. SUBCODE B15 VALVE SUBCODE Z16

17 LER/RO REPORT NUMBER 81 EVENT YEAR 81 SEQUENTIAL REPORT NO. 063 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN D18 FUTURE ACTION Z19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 0000 ATTACHMENT SUBMITTED Y23 NPRD-4 FORM SUB. N24 PRIME COMP. SUPPLIER A25 COMPONENT MANUFACTURER J10526

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The pump was removed and disassembled for inspection. Debris was found

11 lodged in the pump obstructing flow. Preventive maintenance was per-

12 formed and the operability test conducted with satisfactory results.

13 The unit is now in full compliance, and no further action or reporting

14 is required.

15 FACILITY STATUS E28 % POWER 09229 OTHER STATUS NA METHOD OF DISCOVERY B31 DISCOVERY DESCRIPTION Operability Test

16 ACTIVITY RELEASED Z30 CONTENT OF RELEASE Z34 AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

17 PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION NA

18 PERSONNEL INJURIES NUMBER 00040 DESCRIPTION NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION NA

20 PUBLICITY ISSUED N44 DESCRIPTION NA

8107280216 810717
PDR ADOCK 05000366
S PDR

NRC USE ONLY

NAME OF PREPARER C. L. Coggin, Supt. Plt. Eng. Serv. PHONE: 912-367-7851

LER #: 50-366/1981-063
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-063

On 6-25-81, following maintenance on clogged motor cooling water line RHR service water pump E11-C001A was tested for operability. The pump failed to meet acceptance criteria for flow and discharge pressure. Tech Specs section 3.7.1.1.A requires that all pumps in each subsystem be operable. An LCO was declared per Unit 2 Tech Specs 3/4.7.1.1 action A.1. A similar event was reported by LER 50-366/1980-085.

The pump was removed, and upon disassembly a piece of lumber approximately 6" long was found lodged in the impellers. During the same time period the standby diesel service water pump was declared inop also due to debris, and a hole subsequently was found in the traveling water screen. The source of the lumber found in the RHR service water pump cannot be determined. The pump was not damaged, and only routine preventive maintenance was performed. The operability test was conducted, and the pump met acceptance criteria and was returned to service.

There were no effects upon public health and safety due to this event. No further action or reporting is required.