

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 6 7 0 6 2 4 8 8 0 1 7 1 2 1 1 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation at steady state, the 3-A reactor recirculation pump tripped
0 3 due to 2A-K45A relay action. (See T.S. 3.6.F.1) There was no danger to the health
0 4 or safety of the public. There were no redundant systems. 3-B pump was operable.
0 5 Previous similar events: BFR0-50-260/81009, 80018, 81023; 296/81028.
0 6
0 7
0 8
0 9

0 9 SYSTEM CODE C B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE M C T O R X 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER/RO REPORT NUMBER 8 1 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 ACTION TAKEN X 19 FUTURE ACTION X 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 23 ATTACHMENT SUBMITTED Y 24 NPD-4 FORM SUB. N 25 PRIME COMP. SUPPLIER L 26 COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 2A-K45A relay action initiated by RTD high temperature trip. Unit load was reduced
1 1 and the G.E. variable speed M/G set and pump were restarted. The high temperature
1 2 trip setpoint was raised to 120 degrees centigrade. Alarm annunciates at 110 degrees
1 3 centigrade. A special test will be implemented to investigate this problem.
1 4
1 5
1 6
1 7
1 8
1 9
2 0
2 1
2 2
2 3
2 4
2 5
2 6
2 7
2 8
2 9
3 0
3 1
3 2
3 3
3 4
3 5
3 6
3 7
3 8
3 9
4 0
4 1
4 2
4 3
4 4
4 5
4 6
4 7
4 8
4 9
5 0
5 1
5 2
5 3
5 4
5 5
5 6
5 7
5 8
5 9
6 0
6 1
6 2
6 3
6 4
6 5
6 6
6 7
6 8
6 9
7 0
7 1
7 2
7 3
7 4
7 5
7 6
7 7
7 8
7 9
8 0
8 1
8 2
8 3
8 4
8 5
8 6
8 7
8 8
8 9
9 0
9 1
9 2
9 3
9 4
9 5
9 6
9 7
9 8
9 9
100

1 5 FACILITY STATUS E 16 0 9 8 29 30 OTHER STATUS NA 31 METHOD OF DISCOVERY A 32 Operator observed 33
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 6 ACTIVITY CONTENT Z 33 34 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE 37
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 38 39 DESCRIPTION NA 40
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 8 PERSONNEL INJURIES NUMBER 0 0 0 41 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 44 45 DESCRIPTION NA 46
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

2 0 PUBLICITY ISSUED N 47 48 DESCRIPTION NA 49
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NRC USE ONLY

8107280290 810721
PDR ADOCK 05000296
S PDR

Gene Holder

PHONE (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81031 Technical Specification Involved 3.6.E.1

Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 7/24/81

Date of Occurrence 6/24/81 Time of Occurrence 2008 Unit 3

Identification and Description of Occurrence:

3-A reactor recirculation pump tripped due to 2A-K45A relay action.

Conditions Prior to Occurrence:

Unit 1 in refueling outage

Unit 2 at 100%

Unit 3 at 98%

Action specified in the Technical Specification Surveillance Requirements met
due to inoperable equipment. Describe.

Restored 3-A recirculation pump to service within 1½ hours.

Apparent Cause of Occurrence:

The reactor recirculation motor generator set tripped due to 2A-K45A relay
action initiated by RTD high temperature trip.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of
activity, no damage to the plant or equipment, and no resulting significant
chain of events.

Corrective Action: A special test is being written and will be implemented
to investigate this problem. Recurrence control will depend on results from
these investigations. By 6/27/81, the trip setting for the drive motor high
temperature and gen hi temp relays for each M/G set on all three units were
raised to trip at 120°C. Alarm annunciates at 110°C.

Failure Data: BFRO-50-260/81009, 80018, 81023; 296/81028.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

Revision

AM