

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F L S L S 1 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT

CON'T

0 1 L 5 0 5 0 0 0 3 3 5 0 6 0 3 8 1 0 7 0 2 8 1 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 3 While at 100% power, the CEA Motion Inhibit Circuit for Power Dependent

0 3 Insertion Limit (PDIL) failed. T.S. 3.1.3.1 requires the CEA Block Circuit

0 4 to be operable in Modes 1 and 2. However, T.S. 3.1.3.1 and 3.1.3.6 were

0 5 suspended per T.S. 3.10.5 at the time in preparation for moderator

0 5 temperature coefficient testing. This is the first event of this type.

0 7 the second involving the CEA Block Circuit. See LER 335-80-30.

0 8

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP TUBCODE VALVE SUBCODE

R B E G R E L A Y X A Z

LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION

8 1 0 3 0 0 3 L 0

ACTION: FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPDW FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

A Z Z Z 0 0 0 0 N N N S 1 8 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause for this event was the failure of a relay in the Metrascope

1 1 PDIL Circuit. The relay was replaced and the repaired circuit was

1 2 satisfactorily tested within 2 hours of being declared inoperable. No

1 3 further problems were found.

1 4

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

X 1 0 0 MTC TESTING A OPERATOR OBSERVATION

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

Z 2 NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

0 0 0 Z NA

PERSONNEL INJURIES NUMBER DESCRIPTION

0 0 0 NA

LOSS OF OR DAMAGE TO FACILITY DESCRIPTION

Z NA

PLANTIVITY DESCRIPTION

N NA

NAME OF PREPARER P. L. Pace PHONE (305) 552-3754