

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 G A E I H 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 2 1 7 0 7 0 7 8 1 8 0 7 2 1 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Following a reactor scram it was discovered that the instrument root
0 3 valve (B21-F500) for the low condenser vacuum switches (B21-N056A,B) had
0 4 been isolated, thereby, causing the instruments to be in the trip condi-
0 5 tion. There were no effects upon the public health and safety due to
0 6 this event. This is a nonrepetitive occurrence for the subject valve and
0 7 switches.

0 8
0 9
7 8 9
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S H 11 A 12 X 13 V A L V E X 14 A 15 D 16
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 1 23 0 7 2 27 0 3 28 29 L 30 31 32
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 F 19 Z 20 Z 21 0 0 0 0 22 Y 23 Y 24 A 25 C 6 3 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The exact cause of valve misposition is not known. Upon discovery, the
1 1 valve was returned to the correct position. All low condenser vacuum
1 2 root valves have been locked open in a manner to prevent recurrence of
1 3 inadvertent closing.

1 4
7 8 9
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
1 5 G 28 0 0 0 29 NA 30 A 31 Operator Observation
7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
1 7 0 0 0 37 Z 38 NA 39
7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION
1 8 0 0 0 40 NA 41
7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z 42 NA 43
7 8 9 10 80
PUBLICITY ISSUED DESCRIPTION
2 0 N 44 NA 45
7 8 9 10 80
8107310170 810721
PDR ADDOCK 05000321
S PDR
NA
NRC USE ONLY
68 69 80
NAME OF PREPARER C. L. Coggin, Supt. Plt. Eng. Serv. PHONE: 912-367-7851

LER #: 50-321/1981-072
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1981-072

Following a Rx scram it was discovered that the instrument root valve (B21-F500) for the low condenser vacuum switches (B21-N056A&B) had been isolated, thereby, causing the instruments to be in the trip condition. This, in fact, had caused a group 1 isolation and subsequently precipitated the reactor scram. Redundant switches were available and operable. The exact cause of the valve misposition is not known. In order to prevent recurrence the isolation valves for all low condenser vacuum switches on HNP-1&2 have been locked open in a manner to prevent closing the valves without first removing the locking mechanism.

- 2 -