

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4					5
7	8	9						14	15	25										26	30					37	CAT	38			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE											

CON'T

REPORT SOURCE: L 6 0 5 0 - 0 3 2 4 7 0 6 2 9 8 1 8 0 7 2 1 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During the performance of Diesel Generator Actual Loading Test, PT 12.1.1, No. 4
---	---	--

03 Diesel Generator started as required but did not develop generator field voltage.

0 4 | This test simulates a loss of off-site power in conjunction with an ECCS test signal.

0 5 | This event did not affect the health and safety of the public.

06

0 7

Technical Specifications 3.8.1.1, 6.9.1.9b

7	8	9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
1	2	3	4	5	6	7	8	9

0 9 10 11 12 13 14 15 16

LER/RO REPORT	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	NO.
10100000	1011	0161	03	1	10

NUMBER 21 22 23 24 25 26 27 28 29 30 31 32

ACTION FUTURE EFFECT SHUT DOWN ATTACHMENT NPRO-4 PRIME COMP. COMPONENT

KEY	ACTION	ON PLANT	METHOD	NO.	DATE	TIME	BY	REMARKS											
A	18	Z	20	Z	21	0	0	0	0	Y	23	Y	24	N	25	A	6	1	0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | A failed electrical coil in the diesel generator's field shorting device, No. 17,

111 | prevented the generator field from flashing when the diesel started. The coil, Model

1 No. 9103B was replaced and the PT was successfully performed. No cause was deter-

1. mined for the failed coil. Plant documentation shows no history of previous similar

1. and failures, therefore this failure has been attributed to a random failure.

FACILITY	NUMBER	OTHER STATUS	(30) METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	(32)
----------	--------	--------------	--------------------------	-----------------------	------

1 5 F 28 0 5 0 29 NA B 31 Periodic Testing

ACTIVITY	CONTENT	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
RELEASED	OF RELEASE	(35)	(36)

7 8 9 10 11 44 45 46

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	0
		(37)	Z	(38) NA

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

TYPE		DESCRIPTION
1	9	7 (42) NA

7 8 9 10
PUBLCITY (45) 8107310216 810721
PDB ADPCK 05000324 NRC USE ONLY

[illegible]

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: (919) 457-9521

LER ATTACHMENT - RO #2-81-61

Facility: BSEP Unit No. 2

Event Date: 06/29/81

During the initial performance of the periodic test (PT), No. 4 diesel generator did not develop generator field voltage because a failed electrical coil in the generator's field shorting device No. 17 prevented the contacts from opening. This device is designed to short the generator's electrical field when the diesel is not running. When the diesel is started, the device's coil is energized to open electrical contacts and allow the generator field to flash. Whenever a diesel trip is initiated, the device's coil is again energized and the contacts are closed thus collapsing the generator's field. An inspection of this coil on the remaining three diesel generators did not reveal any problems. No specific cause could be determined for the coil failure. This event is considered to be isolated requiring no further corrective action.