

A number line from 1 to 2 with 5 equal intervals, each representing $\frac{1}{6}$. The intervals are labeled $\frac{1}{6}$, $\frac{2}{6}$, $\frac{3}{6}$, $\frac{4}{6}$, and $\frac{5}{6}$.

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

L I C E N S E C O D E 1 4 2 3 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4

L I C E N S E N U M B E R 25 26 L I C E N S E T Y P E 30 57 CAT 58

R E P O R T S O U R C E L 6 0 5 0 0 0 2 5 0

REPORT SOURCE L 6 0 5 0 0 0 2 5 9 7 0 6 1 9 8 1 8 0 7 1 5 8 1 9

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE

RE PORT DATE

NT DESCRIPTION AND PROBABLE CONSEQUENCES 10

with unit 1 in refueling outages

DOCKET NUMBER 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

With unit 1 in refueling outage and units 2 and 3 at steady state 71 percent and 98 percent respectively while performing biaxial seismic switch (HS-3) tests (SI 4.2.J.2), horizontal seismic trigger HST A did not operate. (See T.S. 3.2.J.2) HST A is common to units 1, 2, and 3. There was no danger to the health or safety of the public. Seismic triggers HST B and C were operable. Previous similar event: BFRO-50-259/81034.

SYSTEM CODE: I D 11
 CAUSE CODE: E 12
 CAUSE SUBCODE: G 13
 COMPONENT CODE: I N S T R U 14
 COMP SUBCODE: S 15
 VALVE SUBCODE: Z 16
 EVENT YEAR: 8 1 21
 SEQUENTIAL REPORT NO.: 0 3 6 24
 OCCURRENCE CODE: 0 3 28
 REPORT TYPE: L 30
 REVISION NO.: 0 32
 ON FUTURE ACTION: 18 19 34
 EFFECT ON PLANT: 2 20 35
 SHUTDOWN METHOD: Z 21 36
 HOURS: 0 0 0 0 22 40
 ATTACHMENT SUBMITTED: Y 23 41
 NPRD-4 FORM SUB: N 24 42
 PRIME COMP SUPPLIER: L 25 43
 COMPONENT MANUFACTURER: K 1 3 0 26 47
 USE DESCRIPTION AND CORRECTIVE ACTIONS: 27
 relay transistor in the Kinometrics model HS-3 horizontal seismic trigger failed
 due to moisture condensation inside the housing. The trigger was repaired, SI 4.2.J-2
 successfully completed, and the trigger returned to service within 10 days. Desiccant
 being added to keep down excessive humidity.

1 10 12 17 29 44 45 46 80			2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100			1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100			1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100			1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100			1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100			1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 		
---	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	---	--	--

NAME OF PREPARER

PHONE:

B107310303 B10715
PDR ADDCK 05000259
S PDR

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81036 Technical Specification Involved 3.2.J.2

Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 7/19/81

Date of Occurrence 6/19/81 Time of Occurrence 1500 Unit 1, 2, and 3

Identification and Description of Occurrence:

Seismic trigger HST A failed to operate.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 71%

Unit 3 at 98%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Repaired seismic trigger and returned it to service.

Apparent Cause of Occurrence:

Relay transistor failed due to moisture condensation inside the housing.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The seismic trigger HST A was repaired, SI 4.2.J-2 was successfully performed and the trigger was returned to service. Desiccant is being added to absorb excessive moisture in the housing.

Failure Data: BFRO-50-259/81034

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: 