

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	6	1	0	8	1	8	0	7	0	2	8	1	9		
60	61									68	69						74	75						80		
DOCKET NUMBER											EVENT DATE											REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While the plant was in start-up, 1N62-N009A, Off-gas H<sub>2</sub> Analyzer was  
0 3 | found to be inoperative. The event date is unknown, but reported in-  
0 4 | operative on June 10, 1981. Tech Specs Table 2.1.3.h requires one oper-  
0 5 | able channel. Redundant H<sub>2</sub> Analyzer, 1N62-N009B, was operable. Plant  
0 6 | operation nor the health and safety of the public was not affected by  
0 7 | this event. This is a repetitive event as last reported on Reportable  
0 8 | Occurrence Report No. 50-321/1980-094.

7	8	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9		M	B	11	A	12	X	13	V	A	L	V	E	X	14	F	15	N	16
7		8	9	10		11	12	13		18						19		20		
(17) LER/RO REPORT NUMBER		EVENT YEAR				SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE		REVISION NO.						
21		22		23		24		26		28		29		32						
8		1		—		0		5		0		3		0						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
18		19		20		21		22		23		24		25		26				
X		Z		Z		Z		0		Y		N		N		K				
23		24		25		26		37		41		42		43		44				
								0		0		0				0				
								0								8				
								0								5				
								0								0				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event has been attributed to personnel error. Root

1 1 | Valve N62-F064A was found to be closed. Valve N62-F064A was opened

1 2 | and N62-N009A was returned to service. The unit is now in full

1 3 | compliance.

1 4 |

7 8 9  
FACILITY STATUS 1 5 C 28 % POWER 0 0 0 1 29 OTHER STATUS 30 NA METHOD OF DISCOVERY 31 LA DISCOVERY DESCRIPTION 32 Instrument Technician Observation

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 7 33 7 34 NA 44

LOCATION OF RELEASE (36)  
NA 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		
NUMBER	DESCRIPTION	
(1) (8)	(0) (0) (0) (40)	NA

7		8		9		10		11		12		
LOSS OF OR DAMAGE TO FACILITY												
TYPE		DESCRIPTION										
1	9	Z	42	NA								80

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44)  
8107310318 810702  
PDR ADDCK 05000321  
S PDR  
NRC USE ONLY  
58 69 80

NRC USE ONLY

NAME OF PREPARER

8107310318 810702  
PDR ADCK 05000321  
S PDR

PHONE: 912-367-7781

LER No.: 50-321/1981-056  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket No.: 50-321

Narrative Report  
for LER 50-321/1981-056

While the plant was in start-up, 1N62-N009A, Off-gas H<sub>2</sub> Analyzer, was found to be inoperative. The event date is unknown, but was reported inoperative on June 10, 1981. Tech Specs Table 2.1.3.h, page 2-7, requires one operable channel. Redundant H<sub>2</sub> Analyzer, 1N62-N009B, was operable. Plant operation was not affected as a result of this event. The health and safety of the public was not affected. This is a repetitive event as last reported on Reportable Occurrence Report 50-321/1980-094.

The cause of this event has been attributed to personnel error. Root Valve, N62-F064A, was found to be closed. Valve N62-F064A was opened and N62-N009A returned to service. The unit is now in full compliance with the requirements and no further reporting is required.

A generic review revealed no inherent problems.



Georgia Power

the southern electric system

Edwin I. Hatch Nuclear Plant

July 2, 1981  
PM-81-575


PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-321

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



ATTENTION: Mr. James P. O'Reilly

Pursuant to Section 6.9.1.9.c of Hatch Unit I Technical Specifications,  
please find attached Reportable Occurrence Report No. 50-321/1981-056.

  
M. Manry  
Plant Manager

MM/RTN/mla

xc: J. H. Miller, Jr.  
R. J. Kelly  
W. A. Widner  
J. T. Beckham, Jr.  
C. L. Coggin  
R. D. Baker  
Control Room  
File

IE22  
5/11

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: 912-367-7781

LER No.: 50-321/1981-056  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Pocket No.: 50-321

Narrative Report  
for LER 50-321/1981-056

While the plant was in start-up, 1N62-N009A, Off-gas H<sub>2</sub> Analyzer, was found to be inoperative. The event date is unknown, but was reported inoperative on June 10, 1981. Tech Specs Table 2.1.3.h, page 2-7, requires one operable channel. Redundant H<sub>2</sub> Analyzer, 1N62-N009B, was operable. Plant operation was not affected as a result of this event. The health and safety of the public was not affected. This is a repetitive event as last reported on Reportable Occurrence Report 50-321/1980-094.

The cause of this event has been attributed to personnel error. Root Valve, N62-F064A, was found to be closed. Valve N62-F064A was opened and N62-N009A returned to service. The unit is now in full compliance with the requirements and no further reporting is required.

A generic review revealed no inherent problems.