

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 6 7 0 7 0 1 8 1 8 0 7 2 2 8 1 9
DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while performing instrument checks and observations tests
0 3 (SI 2) and the routine shift inspection, a leak was discovered at the vent nipple
0 4 of the 3A RHR pump room cooler. The cooler was removed from service to repair the
0 5 leak. See T.S. 3.5.D.2, 3.5.B.3, and 3.5.B.5. There was no danger to the health or
0 6 safety of the public. Redundant systems were available and operable. There were
0 7 no previous similar events.

0 8
0 9
SYSTEM CODE C F 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z 14
COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
LER/RO REPORT NUMBER 17 EVENT YEAR 8 1 21 22 SHUTDOWN METHOD Z 21 36 HOURS 7 0 0 0 22 40
ACTION TAKEN B 18 13 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 37 ATTACHMENT SUBMITTED Y 23 41
NPRD-4 FORM SUB. Y 24 42 PRIME COMP. SUPPLIER L 25 43 COMPONENT MANUFACTURER Z 9 9 9 26 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause unknown - there was a crack at the vent nipple on the cooler coil. The crack
1 1 was silver soldered, and a visual inspection performed. This is considered a random
1 2 event and no further recurrence control is required.

1 3
1 4
FACILITY STATUS F 28 9 POWER 0 9 6 29 12 17 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 15 46
DISCOVERY DESCRIPTION 32 Routine test and inspection
ACTIVITY CONTENT RELEASED OF RELEASE 2 33 9 7 34 10 11 AMOUNT OF ACTIVITY NA 35 44 LOCATION OF RELEASE NA 36 45
PERSONNEL EXPOSURES NUMBER 0 0 0 7 37 11 TYPE Z 38 12 DESCRIPTION NA 39 13
PERSONNEL INJURIES NUMBER 0 0 0 40 11 DESCRIPTION NA 41 12
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 9 10 DESCRIPTION NA 43 11
PUBLICATION ISSUED N 44 9 10 DESCRIPTION 45

8107310347 810722
PDR ADOCK 05000296
S PDR

Gene Holder

NAME OF PREPARER

NRC USE ONLY
PHONE: (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 81032 Technical Specification Involved 3.5.B.3
Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 7/31/81
Date of Occurrence 7/1/81 Time of Occurrence 0500 Unit 3

Identification and Description of Occurrence:

While performing SI 2, a crack was discovered at the vent nipple of 3A RHR pump room cooler coil. The cooler was removed from service to repair the leak, rendering the 3A RHR pump inoperable per T.S. 3.5.D.2.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%

Unit 3 at 96%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Met requirements of T.S. 4.5.B.3 and 4.5.B.5.

Apparent Cause of Occurrence:

Cause unknown - there was a crack at the vent nipple on the 3A RHR pump room cooler coil.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The crack was silver soldered and a visual inspection performed. This is considered a random event and no further recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: ALL