

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9
G A E I H 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 14 15 25 26 30 37 CAT 58

CON'T
0 1 2 3 4 5 6 7 8 9
REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 6 1 0 8 1 8 0 6 3 0 8 1 9
60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 1 While the plant was in steady state operation at 2400 MWt, Reactor Build-
0 3 2 ing to Torus Vacuum Breaker Isolation Valve, 2T48-F310, failed open. Tech
0 4 3 Specs 3.6.3 requires that Primary Containment Isolation Valves be operable.
0 5 4 Redundant Reactor Building to Torus Vacuum Breaker Isolation Valve, 2T48-
0 6 5 F311, was operable. Neither plant operation nor public health and safe-
0 7 6 ty were affected. This is a repetitive event as reported on Reportable
0 8 7 Occurrence Report No. 50-366/1981-035.
0 9 8 9

0 9 8 9
SYST. CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S D 11 E 12 E 13 I N S T R U 14 S 15 Z 16
9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
3 1 0 5 1 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 24 A 25 S 3 8 2 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 1 The cause of the event has been attributed to Reactor Building to Torus
1 1 2 Differential Pressure Switch, 2T48-N210. The failure was due to the
1 2 3 switch reset sticking. The switch was cleaned, lubricated and functionally
1 3 4 tested satisfactorily.
1 4 5 8 9

1 5 6 7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
E 28 0 9 8 29 NA A 31 Operator observation
7 8 9 10 12 13 44 45 46 80
1 6 7 8 9
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 NA
7 8 9 10 11 44 45 80
1 7 8 9
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80
1 8 9
PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 40 NA
7 8 9 10 11 12 80
1 9 8 9
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 NA
7 8 9 10 80
1 9 8 9
PUBLICATION DESCRIPTION (45)
ISSUED N 44
7 8 9 10
8107310358 810630
PDR ADDCK 05000366
S PDR
NAME OF PREPARER R. T. Nix, Supt. of Maint. PHONE: 912-367-7781
68 69 80

NRC USE ONLY

LER No.: 50-366/1981-051
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1981-051

On June 10, 1981, while the plant was in steady state operation at 2400 MWt, Reactor Building to Torus Vacuum Breaker Isolation Valve, 2T48-F310, failed open. Tech Specs 3.6.3 requires that Primary Containment Isolation Valves be operable. Redundant Reactor Building to Torus Vacuum Breaker Isolation Valve, 2T48-F311, was operable. Neither plant operation nor public health and safety were affected. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-366/1981-035.

The cause of the event has been attributed to Reactor Building to Torus Differential Pressure Switch, 2T48-N210. The failure was due to the switch, 2T48-N210. The failure was due to the switch reset sticking. The switch was cleaned, lubricated and functionally tested satisfactorily.

A generic review revealed no inherent problems with this type switch.