

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1
A L B K F 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58REPORT SOURCE L 6 0 5 0 0 0 2 6 0 7 0 7 0 1 8 1 8 0 7 2 2 8 1 9
DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

During normal operation at steady state, the 3-A RHR pump room cooler developed a water leak and was isolated for repair, making 3-A RHR pump inoperable. The U-1 B and D pumps were already inoperable because the U-1 torus was drained, thus three RHR pumps located on the unit 2 cross connection became inoperable. (See T.S. 3.5.B-12) There was no danger to the health or safety of the public, no redundant systems, and no previous similar events.

SYSTEM CODE C F 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
EVENT YEAR 8 1 17 LE/R/O REPORT NUMBER 0 3 1 18 SEQUENTIAL REPORT NO. 0 3 1 19 OCCURRENCE CODE 0 3 20 REPORT TYPE L 21 REVISION NO. 0 22
ACTION TAKEN B 18 23 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NRPD-4 FORM SUB. N 24 PRIME COMP SUPPLIER L 25 COMPONENT MANUFACTURER Z 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

The Sil'fos joint on a one quarter inch vent line broke, causing a water leak. The joint was resoldered with Sil'fos, the leak repaired and the system returned to service within 24 hours. This is considered a random failure, and no further recurrence control is required.

FACILITY STATUS E 28 % POWER 0 9 9 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator observed 32
ACTIVITY CONTENT RELEASED OF RELEASE 2 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
PUBLICATION ISSUED N 44 DESCRIPTION NA 45

8107310393 810722
PDR ADOCK 05000260
S PDR

NRC USE ONLY

(205) 729-6134

NAME OF PREPARER Gene Holder

PHONE

LER SUPPLEMENTAL INFORMATION

BERO 50- 260 / 81031 Technical Specification Involved 3.5.B.12

Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 7/31/81

Date of Occurrence 7/1/81 Time of Occurrence 0500 Unit 2

Identification and Description of Occurrence:

The 3-A RHR pump room cooler developed a water leak and was isolated for repair, making 3-A RHR pump inoperable. The Unit 1 B and D pumps were already inoperable because the unit 1 torus was drained, thus three RHR pumps located on the unit 2 cross connection became inoperable.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 96%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Met surveillance requirements of T.S. 4.5.B.12.

Apparent Cause of Occurrence:

The soldered joint on a one quarter inch vent line broke, causing a water leak.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The joint was resoldered, the leak repaired and the system returned to service within 24 hours. This is considered a random failure, and no further recurrence control is required.

Failure Data:

None
Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: ALL