

LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

REPORT SOURCE 1 5 0 5 0 0 0 2 6 0 7 0 6 3 0 8 1 8 0 17 2 2 8 1 9

DOCKET NUMBER 68 69

EVENT DATE 74 75

REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, the RHRSW pump B2 was removed from service to change oil  
0 3 in the motor. This left only one pump (B1) aligned to unit 2 and to unit 3 for  
0 4 standby coolant. Unit 2 was reduced to one pump because the crosstie valve to Unit 1,  
0 5 FCV 74-100 was tagged closed eliminating D-1 and D-2 RHRSW pumps from service. Pump  
0 6 B1 is common to units 2 and 3 for standby coolant. See T.S. 3.5.C.3. There was no  
0 7 danger to the health or safety of the public and no previous similar events.  
0 8

SYSTEM CODE C F (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z Z (14)		COMP SUBCODE Z (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 8 1 (17)		SEQUENTIAL REPORT NO. 0 3 4 (18)		OCCURRENCE CODE 0 3 (19)		REPORT TYPE L (20)		REVISION NO. 0 (21)			
ACTION TAKEN Y (22)		FUTURE ACTION Z (23)		EFFECT ON PLANT Z (24)		SHUTDOWN METHOD Z (25)		HOURS 0 0 0 0 (26)		ATTACHMENT SUBMITTED Y (27)	
NPRD-4 FORM SUB. N (28)		PRIME COMP. SUPPLIER L (29)		COMPONENT MANUFACTURER Z 9 9 9 (30)							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Crosstie valve to unit 1, FCV 1-74-100, was tagged closed, eliminating D-1 and D-2

1 1 | RHRSW pumps from service. Oil was changed in the B2 pump motor and the pump

1 2 | returned to service within one day. This is considered a random event and no

1 3 | recurrence control is required.

1 4 |

8 3  
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)  
1 5 1 0 9 9 NA A Admin observation  
4 3 0 12 13 44 45 46 47  
ACTIVITY CONTENT (33) AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
1 6 2 7 NA  
4 3 10 13 44 45 46 47

PERSONNEL EXPOSURES		EXPL		DESCRIPTION	
1	2	3	4	5	6
0	0	0	0	0	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
		0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44)  
 8107310394 810722  
 PDR ADDCK 05000260  
 S PDR  
 NRC USE ONLY

NAME OF PREPARER Gene Holder

PHONE (203) 729-6134

NRC USE ONLY

(205) 729-6134

0000-017-926

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81034 Technical Specification Involved 3.5.C.3.

Reported Under Technical Specification 6.7.2.b(2) \*Date due NRC: 7/30/81

Date of Occurrence 6/30/81 Time of Occurrence 0600 Unit 2

Identification and Description of Occurrence: The RHRSW pump B2 was removed from service to change the oil in the motor. This left only one pump aligned to unit 2 and to unit 3 for standby coolant. Unit 2 was reduced to one pump because the crosstie valve to unit 1, FCV 74-100, was tagged closed eliminating D-1 and D-2 RHRSW pumps from service.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%

Unit 3 at 92%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Met surveillance requirements of T.S. 4.5.C.4.

Apparent Cause of Occurrence:

Crosstie valve to unit 1, FCV 74-100 was tagged closed, eliminating D-1 and D-2 RHRSW pumps from service, while RHRSW pump was removed from service to change the oil in the motor.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Changed the oil in the motor and returned the pump to service within one day. This is considered a random event and no further recurrence control is required.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: *ALL*