

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5												
3		9						14						15						25						26						30						57		58	
		LICENSEE CODE												LICENSE NUMBER												LICENSE TYPE															

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	5	6	7	0	6	2	6	8	1	8	0	7	2	1	8	1	9
60	61									62	69						74	75						80
DOCKET NUMBER											EVENT DATE							REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)	
0 2	During routine observation of control room panels drywell H <sub>2</sub> -O <sub>2</sub> analyzer
0 3	recorder 2P33-R601A was found inoperative. Tech Specs 3.3.6.4 could
0 4	not be met. A 30-day LCO was declared. The health and safety of the
	public were not affected. A similar event was reported by LER 50-366/

SYSTEM CODE S E 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE X X X X X X 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 1 22		SEQUENTIAL REPORT NO. 0 6 5 26		OCCURRENCE CODE 0 3 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER 0 0 9 6	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The 2P33-R601A recorder was inspected and found to be operating properly.

11 The H<sub>2</sub>-O<sub>2</sub> analyzer was next examined and found inoperable. The gas-flow

regulators were cleaned and readjusted. The analyzer was recalibrated

and returned to service. No further action or reporting is required.

092 NA A1 Operator Observation

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40
		NA	

1		9		Z		42		NA	
---	--	---	--	---	--	----	--	----	--

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45) 8107310400 810721  
2 0 M (44) PDR ADPOCK 05000366  
7 8 9 10 S PDR  
NRC USE ONLY  
68 69 80

NRC USE ONLY

8107310400 810721  
PDR ADJCK 05000366  
S PDR

LER #: 50-366/1981-065  
Licensee: Georgia Power Company  
Facility Name: Edwin I. Hatch  
Docket #: 50-366

Narrative Report  
for LER 50-366/1981-065

During routine observation of control room panels drywell H<sub>2</sub>-O<sub>2</sub> analyzer recorder 2P33-R601A was found inoperative. Tech Specs 3.3.6.4 requires both channels to be operable during power operation. A 30-day LCO was declared. A similar event was reported by LER 50-366/1981-039. The 2P33-R601A recorder was inspected and found to be operating properly.

The H<sub>2</sub>-O<sub>2</sub> analyzer was next examined and found inoperable. The hydrogen and oxygen gas flows in the analyzer were out of adjustment due to partially clogged gas-flow regulators. The regulators were closed, and the gas flows adjusted properly. The analyzer was recalibrated and returned to service. The health and safety of the public were not affected. No further action or reporting is required.