

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 G A E I H 2 2 0 0 0 0 0 0 0 0 1 0 3 4 1 1 1 1 4 5
 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CON'T
 0 1 REPORT SOURCE L 6 0 1 5 0 0 0 3 6 6 7 0 6 2 6 8 1 8 0 1 7 2 1 8 1 9
 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 During steady state power operation the site was notified by the NRC
 0 3 site resident inspector that the procedure used for checking the posi-
 0 4 tions of PSW valves serving safety related equipment (HNP-2-3182, Plant
 Service Water Pump Operability) was inadequate in meeting the require-
 ments of Tech Specs section 4.7.1.2.b. This is a nonrepetitive event.
 There were no effects upon public health or safety due to this event.

SYSTEM CODE W A 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
 9 10 11 12 13 18 19 20
 17 LER/RO REPORT NUMBER 8 1 1 1 0 6 7 0 3 L 0
 21 22 23 24 26 27 28 29 30 31 32
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 The cause of this event was the erroneous determination that HNP-2-3182
 1 1 adequately confirmed the position of the valves serving safety related
 1 2 equipment. HNP-2-3187, Plant Service Water System And Standby Service
 1 3 Water Subsystem Valves Position Verification, was approved and performed
 1 4 on 7-19-81. The unit is now in full compliance.

FACILITY STATUS 28 0 9 2 29 OTHER ST. TUS NA 30 METHOD OF DISCOVERY D 31 DISCOVERY DESCRIPTION Notification by resident inspector 32
 1 5 8 9 10 12 13 44 45 46 80
 ACTIVITY CONTENT RELEASED OF RELEASE 33 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
 1 6 8 9 10 11 44 45 80
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
 1 7 8 9 10 11 12 13 80
 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
 1 8 8 9 10 11 12 80
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
 1 9 8 9 10 80
 PUBLICITY ISSUED N 44 DESCRIPTION 45
 2 0 8 9 10 80
 8107310456 810721 PDR ADOCK 05000366 PDR
 NRC USE ONLY
 58 69 80 91 7-926

LER #: 50-366/1981-067
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-067

On 6-26-81, with the unit in steady state operation (2238 MWt) the site was notified by the NRC site resident inspector that the procedure used for checking the positions of plant service water valves serving safety related equipment (HNP-2-3182, Plant Service Water Pump Operability) was inadequate in meeting the requirements of Tech Specs section 4.7.1.2.b (i.e. by verifying at least once per 31 days that each plant service water system or standby service water subsystem valve (manual, power, or automatic) servicing safety related equipment that is not locked, sealed, or otherwise secured in position is in its correct position.) This is a nonrepetitive event. There were no effects upon public health or safety due to this event.

The cause of this event was the erroneous determination that HNP-2-3182 adequately confirmed the position of the valves serving safety related equipment. A new procedure (HNP-2-3187, Plant Service Water System and Standby Service Water Subsystem Valves Position Verification) was generated as the corrective action. It was approved on 7-18-81, performed on 7-19-81, and placed in the Tech Specs surveillance program on 7-20-81. The unit is now in full compliance with the requirements, and no further reporting or action is required.