

CONTROL BLOCK: 

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 

--	--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	(2)	0	0	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)			
7	8	LICENSEE CODE						14		LICENSE NUMBER										25		LICENSE TYPE					30			57	CAT	58

CON'T

## REPORT

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While operating at 2255 MWt, 2P33-P001B, drywell and torus H<sub>2</sub>-O<sub>2</sub> analyzer recorder, was found to be inoperative. Tech Specs section 3.3.6.4-1 requires both channels to be operative during power operation. The plant was placed in a 30-day LCO. The health and safety of the public was not affected. This is a repetitive event as last reported on LER 50-366/1981-033.

0 8 7 8 0

0	9	S	E	11	X	12	X	13	X	X	X	X	X	X	14	Z	15	Z	16							
7	8	9	10	11	12	13	14	15	16	17	18	19	20													
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																
17	8	1	21	22	—	23	0	5	4	24	25	26	/	27	0	3	28	29	L	30	—	31	0	32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER										
E	18	E	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	X	25	D	0	9	6	26	27	28	29	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event has been attributed to analyzer drift. The

11 analyzer was recalibrated and returned to service.

1	2	
---	---	--

1	3	
---	---	--

1	4	
---	---	--

8 9  
FACILITY STATUS      % POWER      OTHER STATUS (30)      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION (32)

1 5 E (28)      0 9 1 (29)      NA      A (31)      Operator Observation

7 8 9      10 11 12 13      44      45 46      80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34

AMOUNT OF ACTIVITY (35) NA

LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38)
				NA

		7	8	9	10	11	12	13	
		PERSONNEL INJURIES							
		NUMBER						DESCRIPTION	
1	2	0	0	0	0	(4)	0	NA	

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
		NA

1 9 7 8 9 10

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 [N] (44)  
 8107310484 810630  
 PDR ADOCK 05000366  
 S PDR  
 NRC USE ONLY  
 68 69 80

NRC USE ONLY

8107310484 810630  
PDR ADDCK 05000366  
S PDR

68 69  
912-367-7851

0000-7256/05/0000-0000\$05.00/0

LER #: 50-366/1981-054  
Licensee: Georgia Power Company  
Facility Name: Edwin I. Hatch  
Docket #: 50-366

Narrative Report  
for LER 50-366/1981-054

On 6-13-81, while operating at 91% power 2P33-P001B, drywell and torus H<sub>2</sub>-O<sub>2</sub> analyzer recorder, was found to be inoperative. Tech Specs section 3.3.6.4-1 requires both channels to be operative during power operation. The plant was placed in a 30-day LCO. This is a repetitive event as last reported on LER 50-366/1981-033.

The cause of this event has been attributed to analyzer drift. The analyzer, 2P33-P001B, was recalibrated per Comsip Delphi K-IV Hydrogen and Oxygen Analyzer procedure, HNP-2-3882. The analyzer was declared operable and returned to service.

Plant operation was not affected as a result of this event. The health and safety of the public was not affected.

A generic review revealed no inherent drift problems. Unit 1 does not utilize this type of analyzer.