

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F L C R P 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

NT

0 1 7 8

REPORT SOURCE L 6 0 5 0 - 0 3 0 2 7 0 6 2 7 8 1 8 0 7 2 0 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1600 during power escalation after Reactor startup, it was determined that the quadrant

0 3 power tilt exceeded the steady state limit of T.S. 3.2.4 for the time period 1600 to 1616

0 4 There was no effect upon the health or safety of the general public. This was the fourth

0 5 time the quadrant power tilt exceeded the steady state limit, and this is the fifth event

0 6 reported under this Specification.

0 7

0 8

7 8 9 80

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE																		
0	9	R	C	X	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22																			
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
17	8	1	—	0	4	0	/	0	3	L	0	Z	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	Z	25	Z	9	9	9	26
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event is attributed to a Xenon transient following a Reactor trip
1 1 earlier in the day and the transient caused by plant startup. No corrective action
1 2 was required; the event was self correcting.
1 3
1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	F	28	0	3	0	29	NA	44
7	8	9	10	11	12	13	14	15	16
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	44	45	80
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	44
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40	NA	44	45	80
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42	NA	44	45	80	81	82
7	8	9	10	11	12	13	14	15	16
PUBLICITY		TYPE		DESCRIPTION					
2	0	4	44	NA	44	45	80	81	82
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER

PHONE

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

NRC USE ONLY

904/795-6486

SUPPLEMENTARY INFORMATION

Report No.: 50-302/81-040/03L-0

Facility: Crystal River Unit 3

Report Date: July 20, 1981

Occurrence Date: June 27, 1981

Identification of Occurrence:

The quadrant power tilt exceeded the steady state limit contrary to Technical Specification 3.2.4

Conditions Prior to Occurrence:

Mode 1 power operation (30%)

Description of Occurrence:

At 1600 during power escalation, after Reactor startup, it was determined that the quadrant power tilt exceeded the steady state limit. The event was self correcting and the quadrant power tilt was within the steady state limit at 1616.

Designation of Apparent Cause:

The cause of this event is attributed to a Xenon transient following a Reactor trip earlier in the day, and the transient caused by plant startup.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

No corrective action was required to restore the quadrant power tilt to within the steady state limit.

Failure Data:

This was the fourth time the quadrant power tilt exceeded the steady state limit and this is the fifth event reported under this Specification.

/rc