

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2											80
8	9											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

NAME: 65-3250A5B Gene Holder PHONE: (205) 729-6134

NAME OF PREPARER Gene Holder

PHONE: _____

(205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 81040 Technical Specification Involved Table 3.6.H.

Reported Under Technical Specification 6.7.2.B.2 *Date due NRC: 7/25/81

Date of Occurrence 6/25/81 Time of Occurrence 1200 Unit 1

Identification and Description of Occurrence:

While performing MMI-59, snubber No. SS7 was found inoperable.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 100%.

Unit 3 at 97%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe. _____

None

Apparent Cause of Occurrence:

A leak at the threaded connection between the fluid reservoir and the snubber, probably caused by improper thread sealant.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Snubber will be rebuilt and a suitable thread connection sealant used. Inspection intervals for snubbers will be changed per SI 4.6.H because this snubber was found inoperable.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: SA