

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE H H 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO. 0 6 2 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. U 32									
ACTION TAKEN E 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER L 25		COMPONENT MANUFACTURER X 9 9 9	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The pump failed to deliver full flow because the speed control setpoint
1 1 | for the pump turbine had apparently drifted. The trimpot was adjusted to
1 2 | the proper position, the locking nut was tightened and a locking plate was
1 3 | applied to prevent it from working loose. The pump was returned to service
1 4 | at 1245 CDT.

[illegible]

Name of Preparer M D Harding / A M Hill

Phone (615) 842-8317