

U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1 (4) / / / (5)  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT  
 /0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/6/2/2/8/1/ (8) /0/7/2/2/8/1/ (9)  
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On June 23, 1981 during Mode 1 operation, fifteen fire hose stations in the /  
 /0/3/ / Auxiliary building were removed from service, rendering them inoperable contrary /  
 /0/4/ / to T.S. 3.7.14.5, in order to tie-in a new piping system. Since hoses of equiva-/  
 /0/5/ / lent capacity were routed from unaffected hose stations to provide the necessary /  
 /0/6/ / fire protection prior to rendering these hose stations inoperable, the health and/  
 /0/7/ / safety of the public were not affected. This event is reportable pursuant to /  
 /0/8/ / T.S. 6.9.1.9.b. /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /A/B/ (11)	/X/ (12)	/X/ (13)	/Z/Z/Z/Z/Z/Z/ (14)	/Z/ (15)	/Z/ (16)
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17)	/8/1/	/-/ /0/6/0/ / \ /	/0/3/	/L/	/-/ /0/

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
/X/ (18)	/Z/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/Y/ (23)	/N/ (24)	/A/ (25)	/A/1/6/1/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The hose stations were drained to allow a modification tie-in to be made. After /  
 /1/1/ / the modification was completed, all fire hose stations were returned to service. /  
 /1/2/ / \_\_\_\_\_ /  
 /1/3/ / \_\_\_\_\_ /  
 /1/4/ / \_\_\_\_\_ /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/1/0/0/ (29)	/ NA / (30)	/Z/ (31)	/ NA /
ACTIVITY	CONTENT			
RELEASED	OF RELEASE	AMOUNT OF ACTIVITY (35)		LOCATION OF RELEASE (36)
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/	/ NA /
PERSONNEL EXPOSURES				
NUMBER	TYPE	DESCRIPTION (39)		
/1/7/ /0/0/0/ (37)	/Z/ (38)	/ NA /		
PERSONNEL INJURIES				
NUMBER	DESCRIPTION (41)			
/1/8/ /0/0/0/ (40)	/ NA /			
LOSS OF OR DAMAGE TO FACILITY				
TYPE	DESCRIPTION (43)			
/1/9/ /Z/ (42)	/ NA /			
PUBLICITY				
ISSUED	DESCRIPTION (45)			
/2/0/ /N/ (44)	/ NA /			

NRC USE ONLY

/ / / / / / / / / / / / /

NAME OF PREPARER

W. R. CARTWRIGHT

PHONE (703) 894-5151

8108030217 810722  
 PDR ADOCK 05000338  
 S PDR

Virginia Electric and Power Company  
North Anna Power Station, Unit 1  
Docket No. 50-338  
Report No. LER 81-060/03L-0

Attachment: Page 1 of 1

#### Description of Event

On June 23, 1981 with the Unit in Mode 1, fifteen hose stations in the Auxiliary Building (T.S. Table 3.7-7) were removed from service contrary to T.S. 3.7.14.5. This event is reportable pursuant to T.S. 6.9.1.9.b.

#### Probable Consequences of Occurrence

The operability of the fire suppression system ensures that adequate fire protection is available to confine and extinguish fires occurring in any portion of the facility where safety related equipment is located. Since fire hoses from unaffected hose stations were provided to the Auxiliary Building with equivalent capacity as required by T.S. 3.7.14.5 prior to draining the hose stations, the health and safety of the public were not affected.

#### Cause of Event

The Auxiliary building segment of the main fire loop was isolated and drained to perform a new modification tie-in.

#### Immediate Corrective Action

Fire hoses of equivalent capacity were routed into the Auxiliary Building to provide protection to safety related equipment. When the tie-in was completed, the Auxiliary Building hose stations were returned to service.

#### Scheduled Corrective Action

No further action required.

#### Actions Taken to Prevent Recurrence

Not further action required.

#### Generic Implications

There are no generic implications.