



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81027 Technical Specification involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b (1) \*Date due NRC: 7/4/81

Date of Occurrence 6/4/81 Time of Occurrence 0930 Unit 2

Identification and Description of Occurrence

Core spray sparger to PPV d/p switch 2-PdIS-75-56 was found at 1.5 psid (AF decreasing). The T.S. table 3.2.B limit is  $2 \pm 0.4$  psid.

Conditions Prior to Occurrence:

Unit 1 - refueling outage.

Unit 2 - modification outage.

Unit 3 - at 100%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence

Setpoint drift.

Analysis of Occurrence

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The Barton model 288 d/p switch was recalibrated and successfully tested for repeatability. This is considered a random event and no recurrence control is required.

Failure Data:

BFRO-50-259/8087, 8101

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision:

