

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	M	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4		5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
LICENSEE CODE		LICENSE NUMBER										LICENSE TYPE										CAT 58							

CONT

0	1	L	6	0	5	0	0	0	3	6	9	7	0	5	0	8	8	1	8	0	6	0	7	8	1	9		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in Mode 5 the Control Room received a high groundwater alarm. The
0 3 | level was found to be 0.25 feet above the slab elevation. This level re-
0 4 | quired increased surveillance per Technical Specification 4.7.13.b and is
0 5 | reportable per Technical Specification 6.9.1.13(b). The health and safety
0 6 | of the public were not affected.
0 7 |
0 8 |

0	9	X	X	11	C	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE	

17 LER/RO REPORT NUMBER 8 11
18 ACTION TAKEN X 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0
23 ATTACHMENT SUBMITTED Y 24 NPRO-4 FORM 308 N 25 PRIME COMP. SUPPLIER Z 26 COMPONENT MANUFACTURER Z 9 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the alarm was a localized temporary high groundwater level.
1 1 | The level was checked and within one hour the alarm cleared.
1 2 |
1 3 |
1 4 |

1	5	X	29	0	0	0	0	29	Mode 5	30	A	31	Operator Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						

1 6 | Z 33 Z 34 NA 35 NA 36
1 7 | 0 37 0 38 NA 39
1 8 | 0 40 0 41 NA 42
1 9 | Z 43 NA 44
2 0 | N 45 NA 46

NAME OF PREPARER R. W. Ouellette

PHONE: (704) 373-7530

810803C316 810605
PDR ADDOCK 05000369
S PDR