

## LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 580 1 L 6 0 5 0 0 0 2 6 0 7 0 7 0 2 8 1 3 0 7 2 3 8 1 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
CON'T REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while moving equipment through the equipment air lock door,  
0 3 door 238 was not latched properly when the opposite door was opened, resulting in  
0 4 a momentary breach of secondary containment. See T.S. 3.7.C.2. There was no danger  
to the health or safety of the public. There are no redundant systems. Previous  
similar events: WFO-50-250/79020, 80003, 80045.

0 9 S A 11 A 12 X 13 P E N E T R 14 C 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
17 LER/RO REPORT NUMBER 8 1 0 3 2 0 3 L 0  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
H 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 X 9 9 9 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Caused by personnel error. Unknown personnel failed to latch door 238 properly.  
1 1 Latched door and instructed personnel present of correct operation of doors. This  
1 2 is considered a random event and no further recurrence control is required.

1 5 F 21 0 9 3 24 NA A 31 Personnel observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 Z 33 Z 34 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 0 0 0 17 Z 35 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 0 0 0 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 N 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
PRIORITY (CODED) DESCRIPTION 8108030389 810723 PDR ADOCK 05000260 PDR  
NRC USE ONLY

NAME OF PREPARER Gene Holder

PHONE (205) 729-6134

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81032 Technical Specification Involved 3.7.C.2.  
Reported Under Technical Specification 6.7.2.b (4) \*Date due NRC: 8/1/81  
Date of Occurrence: 7/2/81 Time of Occurrence 1000 Unit 2

Identification and Description of Occurrence:

While moving equipment through the equipment air lock door, door 238 was not latched properly when the opposite door was opened, resulting in a momentary breach of secondary containment.

Plant Status at Time of Occurrence:

Unit 1 in refueling outage.

Unit 2 at 93%.

Unit 3 at 94%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe. \_\_\_\_\_

None

Apparent Cause of Occurrence:

Failure of personnel to latch door 238 properly.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Instructed personnel of correct operation of doors.

Failure Data: BFRO-50-260/79020, 80003, 80045.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: ALL