

CONTROL BLOCK:

					(1)
--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	1	(2)	0	0	-	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)
8	9	LICENSEE CODE						14	15	LICENSE NUMBER							25	26	LICENSE TYPE					30	57	CAT	58	

DON'T
 0 1
 8
 REPORT SOURCE L 6 0 5 0 0 0 3 2 1 7 0 7 0 6 8 1 8 0 7 2 3 8 1 9
 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

SYSTEM CODE S A 11		CAUSE CODE A 12		CAUSE SUBCODE A 13		COMPONENT CODE V E S S E L 14		COMP. SUBCODE E 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 6 9		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
ACTION TAKEN H 18		FUTURE ACTION H 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26							

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	G	28	0	0	0	29	NA	A	31	Operator Observation
ACTIVITY CONTENT		RELEASED OF RELEASE			AMOUNT OF ACTIVITY		LOCATION OF RELEASE				
1	6	Z	33	Z	34	NA	35	NA	36		
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39		
PERSONNEL INJURIES		NUMBER		DESCRIPTION							
1	8	0	0	0	40		41	NA	42		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION							
1	9	Z	42		43	NA	44		45		

8108040101 810723
PDR ADOCK 05000321
S PDR NA

LER #: 50-321/1981-069
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1981-069

While Unit I was recovering from a scram, the water level in the suppression pool was approaching the upper limit for normal operation. Because of operation of safety relief valves, the water was hot and the RHR system was operating in the suppression cooling mode. Due to the perturbation caused from this, both level indicators were oscillating and level was hard to determine. When the level stabilized, it was three tenths of an inch below acceptable limits.

Water level was immediately restored to normal limits by normal makeup procedure. This is not a repetitive occurrence and there was no effect on public health or safety due to this event.