

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 S C N E E 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

01 REPORT SOURCE L 0 5 0 0 0 2 6 9 7 0 6 2 4 8 1 8 0 7 2 4 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 On June 24, 1981, a safety-related hydraulic snubber on the Unit 1 "B"
03 atmospheric dump line was discovered to be broken at the rod eye. The
04 inoperability of the snubber only degraded one Main Steam atmospheric dump
05 line. Also all other snubbers and hangers on this line were operable. The
06 redundant train of the Main Steam atmospheric dump line was operable during
07 this event. Thus, the health and safety of the public were not affected.
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
C C E X S U P O R T D Z

17 LER/NO REPORT NUMBER 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
8 1 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
B X Z Z 0 0 0 0 Y Y L G 2 5 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 This incident was apparently caused by vibration. The snubber was repaired
11 and returned to service. Vibration tests were run. The snubber has been
12 pulled for functional testing as part of the 10% test requirement.
13
14

15 FACILITY STATUS 16 % POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
E 0 9 0 NA A Engineer Observation

16 ACTIVITY CONTENT 17 AMOUNT OF ACTIVITY 18 LOCATION OF RELEASE
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
Z Z NA NA

17 PERSONNEL EXPOSURES 18 DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 0 0 Z NA

18 PERSONNEL INJURIES 19 DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
0 0 0 NA

19 LOSS OF OR DAMAGE TO FACILITY 20 DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
Z NA

20 PUBLICITY 21 DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
N NA

21 NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER J. L. Jones

PHONE: (704) 373-8197

DUKE POWER COMPANY
OCONEE UNIT 1

Report Number: RO-269/81-12

Report Date: July 24, 1981

Occurrence Date: June 24, 1981

Facility: Oconee Unit 1, Seneca, South Carolina

Identification of Occurrence: Hydraulic Snubber Inoperable

Conditions Prior to Occurrence: 90% FP

Description of Occurrence: At approximately 1200 hours on June 24, 1981, a safety-related hydraulic snubber on the Unit 1 "B" Main Steam atmospheric dump line was discovered to be broken at the rod eye, thus causing the snubber to be inoperable. This constitutes operation in a degraded mode per Technical Specification 3.14.2 and is thus reportable pursuant to Technical Specification 6.6.2.1.b(2).

Apparent Cause Of Occurrence: Apparently the pipe clamp vibrated below the parallel axis to the snubber resulting in an angle of less than 180°. The vibration of the pipe and the angle of the pipe clamp and rod eye to the snubber caused the threaded end of the rod eye to snap.

Analysis of Occurrence: The probability of occurrence of an earthquake is very low. Also the inoperability of the snubber only degraded one Main Steam atmospheric dump line. The redundant train of the Main Steam atmospheric dump line was operable during this event. All other snubbers and hangers on this line were operable. Hence, the Health and Safety of the public was not affected during operation or shutdown.

Corrective Action: The snubber was repaired and returned to service. Vibration tests were run to determine the frequency and velocity of the vibration and the stress the snubbers/hangers are seeing. The snubber has been pulled for functional testing as part of the 10% test requirements.