

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F L C R P 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

N'T

REPORT SOURCE L 6 0 5 0 - 0 3 0 2 7 0 7 0 3 8 1 8 0 7 2 3 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine shutdown operation it was discovered that Remote Reactor Coolant Temperature Instrument RC-4A-TI2 was inoperable. This created an event contrary to T. S.

0 3

0 4 3.3.3.5. Maintenance was initiated and operability was restored at 2305 on 7/7/81.

0 5 There was no effect upon the health or safety of the general public. This was the

0 6 first occurrence of this type and this is the eighth event reported under this Specification.

0 7

0 8

2 8 0

COMB VALVE

80

SYSTEM CODE I C (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE I (15)		VALVE SUBCODE Z (16)					
EVENT YEAR 8 1 (21) 22		SEQUENTIAL REPORT NO. 0 4 1 (24) 26		OCCURRENCE CODE 0 3 (28) 29		REPORT TYPE L (30) 31		REVISION NO. 0 (32)									
ACTION TAKEN X (18) 13		FUTURE ACTION Z (19) 14		EFFECT ON PLANT Z (20) 15		SHUTDOWN METHOD Z (21) 16		HOURS 0 0 0 0 (22) 23		ATTACHMENT SUBMITTED Y (23) 24		NPRD-4 FORM SUB. N (24) 25		PRIME COMP. SUPPLIER A (25) 26		COMPONENT MANUFACTURER B 0 4 5 (26) 27	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1 0 The cause of this event is attributed to dust and lint in the meter, causing it to

1 1 stick at 584°F. Redundant instruments were available. The instrument was cleaned

1 2 and the functional test was satisfactory. No further corrective action is deemed

1 3 necessary to prevent recurrence.

1 4

80

8 9
FACILITY STATUS (1) (5) (G) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) Shutdown data review DISCOVERY DESCRIPTION (32)
7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE (1) (5) (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION (39)
(1) (7) (0) (0) (0) (37) (Z) (38) NA
7 8 9 11 12 13 80

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)
(1) (4) (0) (0) (0) (40) NA
7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
(9) (Z) (42) NA
7 8 9 10 80

PUBLICITY
ISSUED DESCRIPTION (45)
(2) (0) (N) (44) NA
7 8 9 10 80

8108040631 810723
PDR ADOCK 05000302
S PDR
NRC USE ONLY
68 69 80

NAME OF PREPARER

Victor W. Hernandez PHONE: _____
(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

PHONE:

904/795-6486

SUPPLEMENTARY INFORMATION

Report No.: 50-302/81-041/03L-0
Facility: Crystal River Unit 3
Report Date: July 23, 1981
Occurrence Date: July 3, 1981

Identification of Occurrence:

Remote Reactor Coolant Temperature Instrument was inoperable contrary to Technical Specification 3.3.3.5.

Conditions Prior to Occurrence:

Mode 5 cold shutdown (0%)

Description of Occurrence:

During routine shutdown operation it was discovered during review of shutdown data that Remote Reactor Coolant Temperature Indicator RC-4A-TI2 was inoperable. Maintenance was initiated and operability was restored at 2305 on July 7, 1981.

Designation of Apparent Cause:

The cause of this event is attributed to dust and lint in the meter which caused it to stick at 584°F.

Analysis of Occurrence:

Redundant instruments were available. There was no effect upon the health or safety of the general public.

Corrective Action:

The instrument was cleaned and the functional test was satisfactory. No further corrective action is deemed necessary to prevent recurrence.

Failure Data:

This was the first occurrence of this type and this is the eighth event reported under this Specification.

/rc