

LICENSEE EVENT REPORT

Update Report.

Previous Report Date 7-30-80

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

CON'T

REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 7 0 3 8 0 8 0 7 3 0 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During the performance of PT 6.2.1, Standby Liquid Control (SLC) Relief Valve

0 3 | Operability Test, SLC relief valve, 1-C41-F029B, did not lift. The required lifting

0 4 | setpoint for this valve is 1400 ± 50 psig. A similar event involving this valve was

0 5 | reported in LER 1-79-02 on 2-21-79. This event did not affect the health and safety

0 6 | of the public.

0 7 |

0 8 |

6 8 | Technical Specifications 6.9.1.9b, 3.1.5

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE						
0	9	R	B	E	B	V	A	L	V	E	X	X	H					
7	8	9	10	11	12	13	14	15	16	17	18	19	20					
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.								
17	8	0	—	0	5	7	/	0	3	L	—	1						
21	22	23	24	25	26	27	28	29	30	31	32							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		
E	Z	Z	Z	Z	Z	Z	0	0	0	0	Y	Y	Y	N	L	2	6	5
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Mechanical drift of the valve lifting setpoint was determined as the cause of this

1 1 event. The setpoint was adjusted and the PT was performed satisfactorily. During the

1 2 1981 maintenance outage, the valve was disassembled and examined to determine if any

1 3 mechanical irregularities existed and none were found. Based on the examination it is

1 4 felt no further corrective actions to the event are required.

7	8	9	FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	H	26	0	0	0	29	NA	B	31	Periodic Test											
7	8	9	ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE											
1	6	Z	33	Z	34	NA	NA															
7	8	9	PERSONNEL EXPOSURES				DESCRIPTION															
1	7	0	0	0	37	Z	38	NA														
7	8	9	PERSONNEL INJURIES				DESCRIPTION															
1	8	0	0	0	41	NA																
7	8	9	LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION															
1	9	Z	42	NA																		
7	8	9	PUBL. TY				DESCRIPTION				NRC USE ONLY											
2	0	N	44	NA																		

8108100194 810729
PDR ADQCK 05000325
S PDR

BY M. J. Pastva, Jr.

PHONE: 919-457-9521

LER 1-80-57 SUPPLEMENT ATTACHMENT

Facility: BSEP Unit No. 1

Event Date: 7-3-80

Following this event, the frequency of performing PT 6.2.1 was reduced from once per eighteen months to once per six months to ensure proper calibration. Based on the increased calibration frequency and the results of the past inspection, no further action is required on this event.