

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 L 6 0 5 0 0 0 2 6 0 7 0 7 0 8 8 1 8 0 7 2 8 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a maintenance outage, while performing level switch testing SI 4.1.A-8, prior
0 3 to startup, the scram discharge instrument volume tank level switch 2-LS-85-45F (SDV
0 4 3-gallon alarm switch) failed to operate (NRC IE Bulletin 80-14.) The 25-gallon rod
0 5 block and all 50-gallon scram switches were available and operable. There was no
0 6 danger to the health or safety of the public. Previous similar events: BFR0-50-260/
0 7 80052, 80058.
0 8
0 9

0 9 I B 11 E 12 A 13 I N S T R U 14 S 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Robertshaw level switch model SL-305-EI-X was inoperable. The switch was back
1 1 flushed and failed to operate. This is a newly installed switch, replaced 6/2/81 and
1 2 will be repaired or replaced during a future outage.
1 3
1 4

1 5 C 16 0 0 0 17 Z 18 NA 19 B 20 Surveillance testing.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER: Gene Holder

PHONE: (205) 729-6134

8108100252 810728
PDR ADOCK 05000260
PDR

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81035 Technical Specification Involved NRC LE Bulletin 80-14

Reported Under Technical Specification NRCB 80-14 *Date due NRC: 8/6/81

*Date of Occurrence 7/8/81 Time of Occurrence 0245 Unit 2

Identification and Description of Occurrence:

During the performance of SI 4.1.A-8, level switch testing, prior to startup, the scram discharge volume tank level switch 2-LS-85-45F failed to operate.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 in maintenance outage.

Unit 3 at 98%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Inoperable switch.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Switch will be repaired or replaced during a future outage.

Failure Data: BFR. D-260/80058, 80052.

Retention: Period Lifetime; Responsibility - Document Control Supervisor

*Revision: *AM*