

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

1	6	0	5	0	0	0	2	6	0	7	0	7	0	6	8	1	8	0	7	2	7	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0	2	During normal operation, while moving equipment through the equipment air lock
0	3	door, door 238 was not latched properly when the opposite door was opened, resulting
0	4	in a momentary breach of secondary containment. See T.S. 3.7.C.2. There was no
0	5	danger to the health or safety of the public. There are no redundant systems.
0	6	Previous similar events: BFRO-50-260/79020, 80003, 80045, 81032.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
S	A	A	X	P	E	N	E	T	C	Z					
9	10	11	12	13	14	15	16	17	18	19	20				
EVEN YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	1	0	3	8	0	3	L	0							
21	22	23	24	25	26	27	28	29							
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
H	Z	Z	Z	0	0	0	0	Y	N	L	X	9	9	9	
13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS	
1 0	Caused by personnel error. Unknown personnel failed to latch door 238 properly.
1 1	Relatched and verified proper operation of door. This occurrence is being monitored
1 2	to see if further recurrence control is required.
1 3	
1 4	

FACILITY STATUS (9) E (10)
% POWER (11) 0 (12) 9 (13) 6 (14) 20 (15)
OTHER STATUS (16) NA (17)
METHOD OF DISCOVERY (18) A (19) (20)
DISCOVERY DESCRIPTION (21) Personnel observation (22)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPENDITURES									
NUMBER			TYPE		DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
0	0	0	1	Z	39	NA			

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	NA

LOSSES OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
1-1	2 (42)	NA

ISSUED		PRIORITY	DESCRIPTION	NRC USE ONLY
8	0	(44)	NA	

LEP SUPPLEMENTAL INFORMATION

BFRO 50- 260 / 81038 Technical Specification Involved 3.7.C.2.

Reported Under Technical Specification 6.7.2.b.4. *Date due NRC: 8/5/81

Date of Occurrence 7/6/81 Time of Occurrence 1415 Unit 2

Identification and Description of Occurrence:

While moving equipment through the equipment air lock door, door 238 was not latched properly when the opposite door was opened, resulting in a momentary breach of secondary containment.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 96%

Unit 3 at 95%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Failure of personnel to latch door 238 properly.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Instructed personnel of correct operation of doors.

Failure Data: BFRO-50-260/79020, 80003, 80045, 81032.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: *SM*