

## LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	3	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14							15	25										26	30					57	CAT	58
		LICENSEE CODE							LICENSE NUMBER										LICENSE TYPE									

CON'T

REPORT SOURCE: 0 1 7 8  
DOCKET NUMBER: 60 61 0 5 0 0 0 2 2 0 68 7 0 6 3 0 8 1 74 8 0 7 3 0 8 1 80  
EVENT DATE: 69 70 71 72 73 74 75 76 77 78 79 80  
REPORT DATE: 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a refueling outage, while performed routine calibration of the Emergency  
0 3 | Condenser Vent Monitors, Procedure N1-RTP-20, all four monitors exceeded the  
0 4 | upscale trip set point of .5 mr/hr. Three of the monitors (#111, 112, 121) were  
0 5 | >25 mr/hr but were within the allowable tolerance setting by Technical Specification  
0 6 | 3.2.2. One monitor (#122) tripped at 200 mr/hr which is out of specs and over the  
0 7 | tolerance level. The consequences of the affected equipment were minimal since  
0 8 | the plant was in refuel mode at the time.

SYSTEM CODE 0 9		CAUSE CODE I B		CAUSE SUBCODE E		COMPONENT CODE I N S T R U				COMP. SUBCODE E		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER 17		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 3 0		OCCURRENCE 0 3		REPORT TYPE L		REV. SION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN E		FUTURE ACTION G		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N			
33	34	35	36	37	38	39	40	41	42	43	44		
PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER G 0 8 0											
45	46	47	48										

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | There was a difference found in the response between the test signal and the

1 1 | actual signal. Previous tests were run with a simulated test signal, the test is

1 2 | now run with an ARM calibration device using Cobalt 60 as the source. The procedure

1 3 | has been revised to confirm the trip setting by response to the source. All four

1 4 | monitors were recalibrated, using the actual source, to 20 mr/hr high trip point.

7		8		9								30								32			
FACILITY STATUS						% POWER			OTHER STATUS						METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						
1	5	H	(28)	0	0	0	(29)	NA						B	(31)	Surveillance Testing							
1	2	3		10	11	12	13							45	46								

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z (33) Z (34) NA

AMOUNT OF ACTIVITY (35)

45 NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

7	8	9	11	12	
LOSS OF OR DAMAGE TO FACILITY					(43)
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	

7 8 9 10  
 PUBLICITY  
 ISSUED DESCRIPTION (45)  
 (2) (0) (N) (44) NA

NRC USE ONLY

8108100297 810730  
PDR ADCK 05000220  
S PDR

Richard C. Neild

PHONE: (315) 343-2110 Ext. 1528

600 7-92

ATTACHMENT TO LER 81-30

Cause Description and Corrective Actions (continued)

The discrepancy between the test signal and the actual signal is still under investigation.