

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

U 1 1 L Q A D 1 2 0 0 0 - 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

REPORT SOURCE L 6 U 5 0 0 0 2 5 4 7 0 7 1 7 8 1 8 0 2 3 8 1 9

DOCKET NUMBER 68

EVENT DATE 74

REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing QIS-6, High Drywell Pressure Calibration and Functional Test, pressure switch PS-1-1001-88C tripped at 2.03 psig. This is 0.03 psig higher than the Technical Specification limit in Table 3.1-3. The consequences were minimal because protection was provided by the other pressure switches in the one-out-of-two-twice logic, which were all properly calibrated. The switches initiate a reactor scram upon detecting high drywell pressure.

0	8	7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE	80	
0	9	1	2	3	I	A	E	E	I	N	S	T	R	U	S	Z
7	8	9	10	11	11	12	13	14	15	16	17	18	19	20		
LER/RO REPORT NUMBER		EVENT YEAR			SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER								
E	Z	Z	Z	0	N	Y	N	S	3							
18	19	20	21	22	23	24	25	26	27							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence was instrument setpoint drift. The pressure switch

1 1 was recalibrated and functionally tested. These switches have been found to have

1 2 some setpoint drifting. The frequency of any one switch constantly drifting high

1 3 is minimal therefore no other corrective action is necessary at this time.

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1	5	E	(28)	0	7	6	(29)	NA	(30)	B	(31)	Routine Test	(32)
---	---	---	------	---	---	---	------	----	------	---	------	--------------	------

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) NA
2 6 6 10 12 15 44

LOCATION OF RELEASE (36)
NA
45 8

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)		(39) NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (22) NA

7 8 9 10
PUBLICLY
ISSUED DESCRIPTION (45)
NA
8108110113 810723
PDR ADOCK 05000254
S PD/R
NRC USE ONLY

E. Weinfurter

PHONE: 309-654-2241, ext. 181