

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT

0	1	REPORT SO/RC										L	6	0	5	0	0	C	3	6	6	7	0	7	0	3	8	1	8	0	7	3	0	8	1	9												
7	8											60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On 7-3-81, with the unit in steady state power operation at 2305 MWt and with HNP-2-3309, HPCI Turbine Exhaust Diaphragm Pressure Instrument FT&C, being performed, 2E41-N012A&D HPCI turbine exhaust diaphragm pressure switches actuated at 11.2 and 12.5 psig, respectively. Item 4c of Tech Specs table 3.3.2-2 requires actuation at less than or equal to 10 psig. Plant operation, public health, and safety were not affected. This is a repetitive event as last reported on LER 50-366/1980-137.

0 9
7 8

SYSTEM CODE I B 11
9 10

CAUSE CODE E 12
11

CAUSE SUBCODE E 13
12

COMPONENT CODE I N S T R U 14
13 18

COMP. SUBCODE S 15
19

VALVE SUBCODE Z 16
20

17 LER/RO REPORT NUMBER
21 22

EVENT YEAR 8 1
21 22

SEQUENTIAL REPORT NO. 0 7 0 27
24 26

OCCURRENCE CODE 0 3 28 29

REPORT TYPE L 30 31

REVISION NO. 0 32

ACTION TAKEN E 18 33

FUTURE ACTION Z 19 34

EFFECT ON PLANT Z 20 35

SHUTDOWN METHOD Z 21 36

HOURS 0 0 0 0 22 40

ATTACHMENT SUBMITTED Y 23 41

NPRD-4 FORM SUB. Y 24 42

PRIME COMP. SUPPLIER N 25 43

COMPONENT MANUFACTURER B 0 6 9 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event has been attributed to setpoint drift. The
1 1 | switches were immediately recalibrated per HNP-2-5279, Barksdale Pres-
1 2 | sure Switch Calibration, and functionally tested successfully. The unit
1 3 | is now in full compliance with the requirements and neither any further
1 4 | action nor any further reporting is required.

FACILITY STATUS										% POWER										OTHER STATUS										METHOD DISCOVERY										DISCOVERY DESCRIPTION									
1	5	E	28	0	9	5	29	NA										B	31	Surveillance Test																													

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38		NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40 NA

8 9		11 12		80	
TYPE		DESCRIPTION			
1	9	Z	42	NA	

8 9 10
 PUBLICITY
 ISSUED DESCRIPTION
 2 0 L N 44
 7 8 9 10
 8108110120 810730
 PDR ADCK 05000366
 S PDR NA
 NRC USE ONLY
 68 69 70

NAME OF PREPARER C. L. Coggin, Supt. Plt. Eng. Serv. PHONE: 912-367-7851

LER #: 50-366/1981-070
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-070

On 7-3-81, with the unit in steady state power operation at 2305 MWt and with HNP-2-3309, HPCI Turbine Exhaust Diaphragm Pressure Instrument FT&C, being performed, HPCI turbine exhaust diaphragm pressure switches 2E41-N012A and D actuated at 11.2 and 12.5 psig, respectively. Item 4c of Tech Specs table 3.3.2-2 requires actuation at less than or equal to 10 psig. Redundant switches 2E41-N012B and C were operable and within tolerance. Public health and safety were not affected by this event. Plant operation was not affected by this event. This is a repetitive event, and it was last reported as LER 50-366/1980-137.

The cause of this event has been attributed to setpoint drift. The switches (Barksdale model D2H) were immediately recalibrated as per HNP-2-5279, Barksdale Pressure Switch Calibration, successfully functionally tested, and returned to service. The unit is now in full compliance with the requirement of item 4C of Tech Specs table 3.3.2-2. No further action nor reporting is required.

A generic review of this event revealed no inherent problems. Unit 1 does not use the same type switch for this application.