

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5																			
L I C E N S E E C O D E										L I C E N S E N U M B E R									
R E P O R T S O U R C E										E V E N T D A T E									
D O C K E T N U M B E R										R E P O R T D A T E									
E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S																			
While in Mode 3 routine surveillance discovered that a valve in the centrifugal charging pump discharge line of train B of the Safety Injection System would not cycle. Thus, train B of the Safety Injection System was declared inoperable per T.S.3.5.2 which is reportable per T.S.6.9.1.13 (b). Since train A was available for cooldown while train B was inoperable, this incident had no effect on the safe operation of the plant or the health and safety of the public.																			
S Y S T E M C O D E C A U S E C O D E C A U S E S U B C O D E C O M P O N E N T C O D E C O M P . S U B C O D E V A L V E S U B C O D E																			
S F E X V A L V O P A Z																			
L E T / R O R E P O R T N U M B E R E V E N T Y E A R S E Q U E N T I A L R E P O R T I N G N O . O C C U R R E N C E C O D E R E P O R T T Y P E R E V I S I O N N O .																			
8 1 1 1 6 0 3 L 0																			
A C T I O N T A K E N F U T U R E A C T I O N E F F E C T O N P L A N T S H U T D O W N M E T H O D H O U R S A T T A C H M E N T S U B M I T T E D N P R O - 4 F O R M S U B . P R I M E C O M P . S U P P L I E R C O M P O N E N T M A N U F A C T U R E R																			
A Z Z Z Z 0 0 0 0 N N L R 3 7 8																			
C A U S E D E S C R I P T I O N A N D C O R R E C T I V E A C T I O N S																			
It was found that a mixture of oil and water existed in the gear case of the valve. Since it was determined that water had not entered through the vent, nor was it a result of condensation, it had probably leaked past the gear case seal. The operator was replaced and the valve tested and found to be operating correctly.																			
F A C I L I T Y S T A T U S % P O W E R O T H E R S T A T U S M E T H O D O F D I S C O V E R Y D I S C O V E R Y D E S C R I P T I O N																			
X 0 0 0 Mode 3 B Routine surveillance																			
A C T I V I T Y C O N T E N T A M O U N T O F A C T I V I T Y L O C A T I O N O F R E L E A S E																			
Z Z N/A N/A																			
P E R S O N N E L E X P O S U R E S P E R S O N N E L I N J U R I E S L O S S O F O R D A M A G E T O F A C I L I T Y P U B L I C I T Y																			
N U M B E R T Y P E D E S C R I P T I O N N U M B E R D E S C R I P T I O N T Y P E D E S C R I P T I O N I S S U E D D E S C R I P T I O N																			
0 0 0 Z N/A 0 0 0 Z N/A N N/A																			
N R C U S E O N L Y																			

NAME OF PREPARER Phillip B. Nardoci

PHONE: (704) 373-7432

8108130090 810807
PDR ADDCK 05000369
S PDR