

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION									
<div> <div>01</div> <div>N C M G S</div> <div>200-000000-00</div> <div>3411111</div> <div>4</div> </div>										<div> <div>1</div> <div>2</div> <div>3</div> <div>4</div> <div>5</div> </div>									
L I C E N S E E C O D E										L I C E N S E N U M B E R									
R E P O R T S O U R C E										E V E N T D A T E									
E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S										R E P O R T D A T E									
<div>02</div> <div>While in Mode 3, initial testing of the composite sampler for the containment</div>																			
<div>03</div> <div>ventilation unit condensate drain tank (VUCDT) line determined that the flow</div>																			
<div>04</div> <div>totalizer indicated greater than actual values. It was declared inoperable per</div>																			
<div>05</div> <div>T.S.3.3.3.8 which is reportable per T.S.6.9.1.13 (b). Analysis of a represent-</div>																			
<div>06</div> <div>tative, composite sample of the volume released confirmed that the contents</div>																			
<div>07</div> <div>released were within specified limits for operation. Thus, the safe operation</div>																			
<div>08</div> <div>of the plant and the health and safety of the public were not affected.</div>																			
<div>09</div> <div> <div>SYSTEM CODE</div> <div>CAUSE CODE</div> <div>CAUSE SUBCODE</div> <div>COMPONENT CODE</div> <div>COMP. SUBCODE</div> <div>VALVE SUBCODE</div> </div>																			
<div>10</div> <div> <div>LER/RO REPORT NUMBER</div> <div>EVENT YEAR</div> <div>SEQUENTIAL REPORT NO.</div> <div>OCCURRENCE CODE</div> <div>REPORT TYPE</div> <div>REVISION NO.</div> </div>																			
<div>11</div> <div> <div>ACTION TAKEN</div> <div>FUTURE ACTION</div> <div>EFFECT ON PLAN</div> <div>SHUTDOWN METHOD</div> <div>HOURS</div> <div>ATTACHMENT SUBMITTED</div> <div>NRC-4 FORM SUB.</div> <div>PRIME COMP. SUPPLIER</div> <div>COMPONENT MANUFACTURER</div> </div>																			
<div>12</div> <div>CAUSE DESCRIPTION AND CORRECTIVE ACTIONS</div>																			
<div>13</div> <div>In addition to a leaking pneumatic fitting, the Foxboro totalizer (Model 14A)</div>																			
<div>14</div> <div>apparently lacks "stops" so that it continues to run after flow has stopped.</div>																			
<div>15</div> <div>The fitting was repaired, and the totalizer will be replaced with one by</div>																			
<div>16</div> <div>another manufacturer. The appropriate action statement was implemented, and</div>																			
<div>17</div> <div>until replacement all liquid in the VUCDT will be transferred to the floor drain</div>																			
<div>18</div> <div>tank for release.</div>																			
<div>19</div> <div> <div>FACILITY STATUS</div> <div>% POWER</div> <div>OTHER STATUS</div> <div>METHOD OF DISCOVERY</div> <div>DISCOVERY DESCRIPTION</div> </div>																			
<div>20</div> <div> <div>ACTIVITY RELEASED</div> <div>CONTENT</div> <div>AMOUNT OF ACTIVITY</div> <div>LOCATION OF RELEASE</div> </div>																			
<div>21</div> <div> <div>PERSONNEL EXPOSURES</div> <div>NUMBER</div> <div>TYPE</div> <div>DESCRIPTION</div> </div>																			
<div>22</div> <div> <div>PERSONNEL INJURIES</div> <div>NUMBER</div> <div>DESCRIPTION</div> </div>																			
<div>23</div> <div> <div>LOSS OF OR DAMAGE TO FACILITY</div> <div>TYPE</div> <div>DESCRIPTION</div> </div>																			
<div>24</div> <div> <div>PUBLICITY ISSUED</div> <div>DESCRIPTION</div> </div>																			
<div>25</div> <div> <div>NAME OF PREPARER</div> <div>PHONE</div> </div>																			