

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONFIDENTIAL

REPORT SOURCE: L 6 0 5 0 0 0 3 2 1 7 0 7 0 8 8 1 8 0 7 3 1 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			
0	9	Z	Z	E	B	Z	Z	Z	Z	Z	Z	Z	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	8	1		0	7	7	/	0	3	L	0						
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
C	F	Z	Z					0	0	0	Y	N	Z	Z	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS
[1] [5] [E] (28)

% POWER
[0] [6] [0] (29)

OTHER STATUS (30)
N/A

METHOD OF DISCOVERY
[B] (31)

DISCOVERY DESCRIPTION (32)
Routine Surveillance

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	37	Z	38	N/A	39	

8 9		11 12		
TYPE		DESCRIPTION		(43)
1	9	Z	(42)	N/A

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
[2][0] | N |(44)| N/A

LER No.: 50-321/1981-077
Licensee: Georgia Power Company
Facility: Plant E.I. Hatch
Docket No.: 50-32

Narrative Report
for LER 50-321/1981-077

While the unit was in steady state operation at 1442 MWt, it was discovered that the Unit 1 Radwaste loading dock was contaminated. Contamination levels ranged from 500-4300 dpm/100 cm² smearable. There were no effects upon public health and safety due to this event. This is a nonrepetitive event.

The cause of this event was due to an inadequate seal around the shield doors to the conveyor aisles. When the radwaste drums were washed down prior to shipment some of the wash water containing resin seeped out from underneath the doors onto the loading dock. An MR was written to replace or repair the seals. The dock was decontaminated.

There were no releases outside the protected area due to this event. The seals on the Unit 2 conveyor aisles shield doors were also inspected and found to be in good condition.