

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	6	6	7	0	7	1	9	8	1	8	0	8	0	6	8	1	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While the plant was in steady state operation at 2121 MWt, the Drywell
0 3 and Torus Temperature Recorder, 2T47-R627, was found inoperative. Tech
0 4 Specs Section 3.3.6.4 requires two operable channels. The redundant re-
0 5 corder was operable. Plant operation was placed in a 30 day LCO as a re-
0 6 sult of this event. The health and safety of the public was not affected.
0 7 This is a repetitive event as last reported on Reportable Occurrence
0 8 Report No. 50-366/1981-047.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
0	9	I	C	E		G		I	N	S	T	R	U	R	Z		
7	8	9	10	11	12	13	14	15	16			17	18	19	20		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		8	1			0	7	2		0	3	L			0		
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER			
D	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	A	25
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event has been attributed to component failure. The

1 1 | logic board was found defective. The board was replaced, the recorder

1 2 | recalibrated and returned to service.

1 3 |

1 4 |

1 5 E 28 0 8 7 29 NA 30 A 31 Operator observation 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 33 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA

PUBLICITY
ISSUED DESCRIPTION NA

(7) (0) (N) (44)

68 69

NRC USE ONLY

LER No.: 50-366/1981-072.
Licensee: Georgia Power Company
Facility: Plant E. I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1981-072.

While the plant was in steady state operation at 2121 MWt, the Drywell and Torus Temperature Recorder, 2T47-R627, was found inoperative. Tech Specs Section 3.3.6.4 requires two operable channels. The redundant recorder was operable. Plant operation was placed in a 30 day LCO as a result of this event. The health and safety of the public was not affected. This event is repetitive as last reported on Reportable Occurrence Report No. 50-366/1981-047.

The cause of this event has been attributed to component failure. The logic board was found defective. The board was replaced, the recorder recalibrated and returned to service. A similar model recorder by the same vendor is used on Unit I. A generic review revealed no inherent problems.