

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
<div> <div>01</div> <div>N C M G S 1</div> <div>200-000000-00</div> <div>341111</div> <div>4</div> <div>5</div> </div>										<div> <div>L</div> <div>05000369</div> <div>7070681</div> <div>8080581</div> <div>9</div> </div>									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																			
While Mode 3, during a check of pressure gauges suspected of not being properly																			
isolated, a main steam pressure transmitter was inadvertently isolated resulting																			
in the channel being declared inoperable. This violates T.S.3.3.2 which is																			
reportable per T.S.6.9.1.13 (b). Since the low steam line pressure safety in-																			
jection trip was blocked, the isolation of one channel of steam generator "D"																			
main steam line pressure had no effect on the safe operation of the plant or the																			
health and safety of the public.																			
<div> <div>C C</div> <div>11</div> <div>A</div> <div>12</div> <div>C</div> <div>13</div> <div>I N S T R U</div> <div>14</div> <div>T</div> <div>15</div> <div>Z</div> <div>16</div> </div>										<div> <div>81</div> <div>1</div> <div>1</div> <div>3</div> <div>03</div> <div>L</div> <div>0</div> </div>									
<div> <div>E</div> <div>7</div> <div>G</div> <div>19</div> <div>Z</div> <div>20</div> <div>Z</div> <div>21</div> <div>0000</div> <div>22</div> <div>Y</div> <div>23</div> <div>N</div> <div>24</div> <div>L</div> <div>25</div> <div>Z999</div> <div>26</div> </div>										<div> <div>03</div> <div>L</div> <div>0</div> </div>									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																			
The error was caused by a misunderstanding in a phone conversation about which																			
instruments needed to be isolated. The affected channel of the main steam safety																			
injection trip logic was placed in the tripped position, and the transmitter re-																			
turned to service. A procedure was devised to prevent similar misunderstandings																			
in the future, and personnel involved were cautioned to be more careful in trans-																			
mitting information.																			
<div> <div>X</div> <div>28</div> <div>0000</div> <div>29</div> <div>Mode 3</div> <div>30</div> <div>B</div> <div>31</div> <div>Routine Surveillance</div> <div>32</div> </div>										<div> <div>Z</div> <div>33</div> <div>Z</div> <div>34</div> <div>N/A</div> <div>35</div> <div>N/A</div> <div>36</div> </div>									
<div> <div>0000</div> <div>37</div> <div>Z</div> <div>38</div> <div>N/A</div> <div>39</div> </div>										<div> <div>0000</div> <div>40</div> <div>N/A</div> <div>41</div> </div>									
<div> <div>Z</div> <div>42</div> <div>N/A</div> <div>43</div> </div>										<div> <div>N/A</div> <div>44</div> </div>									
<div> <div>N</div> <div>44</div> <div>N/A</div> <div>45</div> </div>										<div> <div>N/A</div> <div>46</div> </div>									

8108130227 810805  
PDR ADOCK 05000369  
S PDR

NAME OF PREPARER

Phillip B. Nardoci

PHONE: (704) 373-7432