

Update Report; Previous Report Date 7-9-81  
(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Update Report; Previous Report Date 7-9-81  
(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	M	B	X		Z		V	A	L	V	E	X	F	N
		9	10	11	12	12	13	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
17		8	1		0	6	1		0	3	L		1		
		21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
X		Z		Z		Z		0	0	0	0	Y		N	N
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

NAME OF PREPARED: W. L. McGinn, Supt. Plt. Eng. Serv. PHONE: 912-367-7851

LER #: 50-321/1981-061, Rev. 1  
Licensee: Georgia Power Company  
Facility Name: Edwin I. Hatch  
Docket #: 50-321

Narrative Report  
for LER 50-321/1981-061, Rev. 1

On 6-29-81, while the plant was in steady state operation at 2400 MWt and while performing HNP-1-3604, GE H<sub>2</sub> Analyzer Calibration, analyzer N62-N009A was found out of calibration, and N62-N009B was found inoperative. The event date is unknown but was reported inoperative on 6-29-81. Tech Specs table 2.1.3.h, page 2-7, requires one operable channel. Plant operation was not affected as a result of this event. The health and safety of the public was not affected. This is a repetitive event as last reported on LER 50-321/1981-056.

The cause of this event was analyzer A out of calibration and analyzer B inoperative. MR 1-81-5048 was written to correct the problem. The analyzers were repaired, calibrated, and successfully returned to service.