

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	F	L	C	R	P	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																									
2		8		9							14							15							25							26							30							57							CAT 58	
				LICENSEE CODE														LICENSE NUMBER														LICENSE TYPE																						

ON'T

REPORT SOURCE L 6 0 5 0 ~ 0 3 0 2 7 0 7 1 0 8 1 8 0 8 0 4 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0617 during routine shutdown operation, it was determined that Reactor Building Pres-  
0 3 | sure Indicator BS-17-PI was inoperable contrary to T.S.3.3.3.6. Maintenance was  
0 4 | initiated, and operability was restored at 1030. Redundancy was provided by BS-16-PI.  
0 5 | There was no effect upon the health or safety of the general public. This was the  
0 6 | first occurrence for BS-17-PI, and this is the third event reported under this  
0 7 | specification.

08 | \_\_\_\_\_ 81

7 8 9

0 9

2 8

SYSTEM CODE

I D 11

9 10

CAUSE CODE

X 12

11

CAUSE SUBCODE

Z 13

12

COMPONENT CODE

I N S T R U 14

13 18

COMP. SUBCODE

T 15

19

VALVE SUBCODE

Z 16

20

(17) LER/RO REPORT NUMBER 81 — 045 / 03 L — 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER							
F	18	X	19	Z	21	0000	22	Y	23	N	24	A	25	L	1	3	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event is attributed to instrument drift. The instrument was

1 1 recalibrated, and the functional test was satisfactory. A modification (REI 80-7-4) is

1 2 being developed for replacement of R3 pressure transmitters.

1 3

1 4

8 9  
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)  
1 5 G 0 0 0 NA A Operator Observation

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 Z 34 NA NA

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	C	00	37	Z	38	NA			

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

7		8		9		10		11		12		
LOSS OF OR DAMAGE TO FACILITY						(43)						
TYPE		DESCRIPTION										
1	2	3	4	5	6	7	8	9	10	11	12	
	9	Z	(42)	NA								

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44) NA

NRC USE ONLY

8108130234 810804  
PDR ADOCK 05000302 PARER Victor A. Hernandez PHONE 904/795-6486  
S PDR (SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

Report No. 50-302/81-045/03L-0

Facility: Crystal River Unit #3

Report Date: August 4, 1981

Occurrence Date: July 10, 1981

Identification of Occurrence:

Reactor Building Pressure Indicator was inoperable contrary to Technical Specification 3.3.3.6.

Conditions Prior to Occurrence:

Mode 3

Description of Occurrence:

At 0617 during routine shutdown operation, it was determined that Reactor Building Pressure Indicator BS-17-PI was not indicating correctly. Maintenance was initiated, and operability was restored at 1030.

Designation of Apparent Cause:

The cause of this event is attributed to instrument drift.

Analysis of Occurrence:

Redundancy was provided by Reactor Building Pressure Indicator BS-16-PI. There was no effect upon the health or safety of the general public.

Corrective Action:

The instrument was recalibrated, and the functional test was satisfactory. A modification (REI 80-7-4) is being developed for replacement of Reactor Building Pressure Transmitters.

Failure Data:

This was the first occurrence for BS-17-PI, and this is the third event reported under this specification.