

## LICENSEE EVENT REPORT

LER 81-18/3L

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	T	V	Y	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5					
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58			59

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 2 7 1 7 0 7 1 3 8 1 8 0 8 1 2 8 1 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During monthly surveillance per T. S. 4.5.A.1.C, it was discovered that Core Spray Valve V14-11A could not be reopened from the control room due to a tripped breaker, leaving Core Spray Subsystem A inoperable contrary to T. S. 3.5.A.1. V14-11A breaker was immediately closed and the valve reopened. Core Spray Subsystem B was continuously operable. There were no consequences to the health and safety of the public as a result of this event. There were no previous reportable occurrences of this type.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		
		S	F	X		Z	I	C	K	T	B	R	K	A	Z		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
23	24	25	26	27	28	29	30	31	32								
		8	1	0	1	8	/	0	3	L							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
X	H	Z	Z	0	0	0	0	N	N	A	W	1	2	0			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event was caused by operator holding the control switch closed, which repeatedly  
1 1 | energized the motor causing excessive inrush currents which tripped the molded case  
1 2 | breaker. The corrective action was to reset the breaker and reopen the valve with-  
1 3 | out holding the switch. Precautions on the operation of MOV's will be reviewed  
1 4 | with the operators.

8 9  
FACILITY STATUS 30  
1 5 E 28  
7 8 9  
10 11 12 13  
% POWER 29  
1 0 0  
OTHER STATUS 30  
NA  
44  
METHOD OF DISCOVERY 31  
B  
45 46 47 48 49 50  
DISCOVERY DESCRIPTION 32  
Operator Observation  
80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 10 34 NA

7 8 9 10 11 12

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

45 50 55 60 65 70 75 80 85 90 95 100

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	Z
			NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
		0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
Z	(42) NA	

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44) NA  
NRC USE ONLY

NRC USE ONLY

8108200307 810812  
PDR ADCK 05000271  
S PDR

EPAPER Warren P. Murphy

PHONE: (802) 257-7111

0007-1226(200809)30:05;1-B