

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	1	8	7	0	5	0	2	8	1	8	0	8	1	1	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	At 1109 during normal operation, the rounds man discovered the linkage																																																																														
6	3	for the Discharge Damper to 22 ECCS Pump Room Exhaust Fan needed adjust-																																																																														
0	4	ment. The linkage caused the damper to fail shut rendering the fan																																																																														
0	5	inoperable (T.S. 3.7.7.1). The damper was repaired and the fan was																																																																														
0	6	returned to service at 1400 on 5-4-81. The redundant fan remained																																																																														
0	7	operable during the event. Similar events: None.																																																																														

0	9	A	A	E	B	V	A	L	L	V	E	X	N	G	8	1	0	2	6	0	3	X	2	E	E	Z	Z	0	0	0	0	N	N	A	J	0	9	0
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Investigation showed that the linkage rod had shifted from its proper																																																																														
1	1	position. The linkage was repaired and adjusted to operate the damper																																																																														
1	2	properly. A surveillance test procedure exists for verification of the																																																																														
1	3	damper's operability and a Preventive Maintenance Procedure to maintain																																																																														
1	4	the linkage has been instituted.																																																																														

1	5	E	1	0	0	NA	A	Operator Observation
1	6	Z	Z	NA	NA			
1	7	0	0	0	Z	NA		
1	8	0	0	0	NA			
1	9	Z	NA					
2	0	N	NA					

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 808108200338 810811
PDR ADJCK 05000318
S PDR

C L. Rayburn

PHONE (301) 269-4803