

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALJMF2 200-0000-00 341111 4 5

REPORT SOURCE L 605000364 7072081 3081781 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | At 0315 on 7/20/81, the Turbine Driven Auxiliary Feed Water Pump Exhaust
03 | Radiation Monitor (R60D) was declared inoperable due to a printed circuit
04 | card failure. Tech. Spec. 3.3.3.1 requires Radiation Monitor R60D to be
05 | operable. Tech. Spec. 3.3.3.1 action statement requirements were met.
06 | Health/Safety of the public was not affected.

07 |

03 |

09 SYSTEM CODE BA 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE ZZZZZZ 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 81 21 22 23 2429 25 26 27 2803 29 30 31 32 33

ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 000 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z999 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The event was caused by a short between the check source mounting hardware
11 | and the PC card which shorted out a diode. The short was repaired and
12 | following a channel check, the TDAFWP Exhaust Radiation Monitor R60D was
13 | returned to service at 0930 on 7/23/81.

14 |

15 FACILITY STATUS G 28 % POWER 000 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

20 PUBLICITY ISSUED DESCRIPTION N 44 45

8108240105 810817
PDR ADCK 05000364
PDR R

W. G. Hairston, III

PHONE: (205) 899-5156

NRC USE ONLY