

LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	4			5
7	8	14						15	25										26	30			57		58		
LICENSEE CODE		LICENSE NUMBER										INSE TYPE		CAT													

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 8 0 4 8 1 8 0 8 3 1 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a scram recovery when an attempt was made to place the "A" RHR SW subsystem into
0 3 service for use in suppression pool cooling, the subsystems' pumps could not be started
0 14 due to a pump suction header low pressure lockout signal from the header pressure
0 5 switch, 2-SW-PS-1175, Model No. D2T-M150-SS, despite a normal suction header pressure.
0 6 The "B" RHR SW subsystem was utilized for suppression pool cooling and the plant was in
0 7 cold shutdown within the following 24 hours. This event did not affect the health and
0 8 safety of the public. Technical Specifications 3.7.1.1, 6.9.1.9b

0	9	SYSTE 1 CODE		W	A	11	CAUSE CODE		E	12	CAUSE SUBCODE		B	13	COMPONENT CODE				P	I	P	E	X	Y	14	COMP. SUBCODE		A	15	VALVE SU3CODE		Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
17		21		24		28		30		32		33		34		35		36		40		41		42		43		44					
8		1		0		7		8		0		3		L		0		D		Z		N		Y		Z		B					
21		22		23		24		25		26		27		28		29		30		31		32		33		34		35					
37		38		39		40		41		42		43		44		45		46		47		48		49		50		51					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The threaded plug in the switch diaphragm housing became loose and allowed the diaphragm
1 1 fluid to leak out and caused the switch to sense a low pressure. The housing was
1 2 refilled, the plug reinstalled and the housing was checked for leaks with none found.
1 3 The other RHR SW suction header pressure switches were checked with no problems found.
1 4 Plant documentation shows this event is isolated; therefore, no further corrective
2 8 action is required. 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	28	0	0	0	29	NA	30
7	8	9	10	11	12	13	14	15	16
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		TYPE		DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		TYPE		DESCRIPTION					
1	8	0	0	0	40		41	NA	42
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42		43		44	NA	45
7	8	9	10	11	12	13	14	15	16
PUBLICATION		ISSUED		DESCRIPTION					
2	0	N	44		45		46	NA	47
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER

M. J. Pastva, Jr.

PHONE

(919) 457-9521