

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A L J M F | 2 2 0 0 - 0 0 0 0 0 - 0 0 3 | 4 1 1 1 1 4 | 5

REPORT SOURCE L 6 | 0 5 0 0 0 3 6 4 7 | 0 8 0 1 8 1 3 | 0 8 3 1 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | At 1825 on 8/1/81, the instrumentation loop associated with the refueling water storage

0 3 | tank level transmitter (LT-501) was declared inoperable when the level indicator

0 4 | (LI-4075A) failed high. Tech. Spec. 3.3.3.8, in part, requires the instrumentation loop

0 5 | to be operable. Tech. Spec. 3.3.3.8 action statement requirements were met. Health/

0 6 | safety of the public was not affected.

0 9 | I D 11 | C 12 | Z 13 | I N S T R U 14 | T 15 | Z 16

17 | 8 1 | 0 3 3 | 0 3 | L | 0

X 18 | Z 19 | Z 20 | Z 21 | 0 0 0 0 | N 22 | N 23 | N 24 | N 25 | W 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The event was caused by moisture entering the transmitter junction box during a rainstorm.

1 1 | The junction box was dried and Instrumentation loop LT-501 was returned to service at

1 2 | 0510 on 8/2/81. The junction box has subsequently been sealed to prevent recurrence

1 3 | of this event.

1 4 | 1 29 | 1 0 0 29 | N/A 30 | A 31 | Operator Observation 32

1 5 | Z 33 | Z 34 | N/A 35 | N/A 36

1 6 | 0 0 0 37 | Z 38 | N/A 39

1 7 | 0 0 0 40 | N/A 41

1 8 | Z 42 | N/A 43

2 0 | N 44 | N/A 45

8109070450 810831
 PDR ADDCK 05000364
 S PDR

NRC USE ONLY