

## LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

01 REPORT SOURCE 1 6 0 5 0 0 0 3 1 1 7 0 8 0 8 8 1 8 0 8 2 8 8 1 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On August 8 and August 9, 1981, while performing surveillance procedure SP(0)4.6.1.3  
03 on the 100' elevation containment air lock, it was determined that the leakage rate  
04 exceeded the limit of 0.05 La at the design pressure of 47.0 psig as required by  
05 technical specification 3.6.1.3.b. At 2015 and 1230 hours, on August 8 and August 9,  
06 respectively, the air lock was declared inoperable and action statement 3.6.1.3  
07 was entered.

08  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

09  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER NO REPORT NUMBER 8 1  
18 EVENT YEAR 8 1  
19 CAUSE CODE S A 11  
20 CAUSE SUBCODE E 12  
21 COMPONENT CODE B 13  
22 COMPONENT CODE P E N E T R 14  
23 COMP SUBCODE A 15  
24 VALVE SUBCODE Z 16  
25 SEQUENTIAL REPORT NO 0 8 3  
26 OCCURRENCE CODE 0 3  
27 REPORT TYPE L  
28 REVISION NO 0  
29 ACTION TAKEN E 18  
30 FUTURE ACTION Z 19  
31 EFFECT ON PLANT Z 20  
32 SHUTDOWN METHOD Z 21  
33 HOURS 0 0 0 0  
34 ATTACHMENT SUBMITTED Y 23  
35 NRC-4 FORM SUB N 24  
36 PRIME COMP. SUPPLIER L 25  
37 CONFO. MANUFACTURER C 3 1 0  
38 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 On August 8, it was determined that the outer door seal had come out of its channel.  
11 The door seal was repaired and tested satisfactorily. On August 9, it was discovered  
12 that a door cam roller had moved off its track. The door cam roller was realigned.  
13 The leak rate test was then performed satisfactorily. At 2030 and 1836 hours on  
14 August 8 and August 9, respectively, action statement 3.6.1.3 was terminated.

15 FACILITY STATUS E 28  
16 % POWER 0 7 7 29  
17 OTHER STATUS N/A 30  
18 METHOD OF DISCOVERY B 31  
19 DISCOVERY DESCRIPTION Leak Rate Test. 32

16 ACTIVITY CONTENT Z 33  
17 RELEASED OF RELEASE Z 34  
18 AMOUNT OF ACTIVITY NA 35  
19 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37  
18 TYPE Z 38  
19 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40  
19 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42  
20 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44  
21 DESCRIPTION NA 45

NRC USE ONLY

NAME OF PREPARER

Frank Dickey

PHONE

609-935-5100

810909569