

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	C	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	3	1	7	7	0	8	0	3	8	1	8	0	9	0	1	8	1	9
60	61								68	69					74	75							80
DOCKET NUMBER										EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1615, during normal operation, the Control Room Operator discovered
0 3 | that the plant computer had failed, rendering the incore detector sys-
0 4 | tem inoperable (T.S. 3.3.3.2). The computer was returned to service
0 5 | at 1803. The excore detector system remained operable during this
0 6 | event. No similar events have been reported.

7 8 9

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

R B (11) X (12) X (13) X X X X X X (14) Z (15) Z (16)

9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

81 061 03 L 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER						
X	18	X	19	Z	Z	22	Y	23	N	24	N	25	W	1	2	0
22	18	24	19	25	26	17	40	41	42	43	44					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Westinghouse P-250 computer stopped upon a Rapid Access Disk (RAD)

1 1 transmission error. Suspect high ambient room temperature caused inter-

1 2 mittent marginal RAD circuit operation. No failed component was found.

1 3 Further action is dependent on return of the symptom which will allow

1 4 troubleshooting.

7	8	9	FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	5		E (28)		1	0	0 (29)	NA	A (31)	Operator Observation		

7 8 10 12 13 44 45 46 8

ACTIVITY CONTENT

RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 Z 34 NA NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		0	37	Z
			38	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1		9		Z		42		NA		43	
7	8	9	10								

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION

PUBLICITY

NBC USE ONLY

ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44) NA		

8109110146 810901
PDR ADOCK 05000317 S. Lagiewski/P. G. Rizzo
PHONE: (301) 269-4747/4786

LER NO. 81-61/3L
DOCKET NO. 50-317
LICENSE NO. DPR-53
EVENT DATE 08-03-81
REPORT DATE 09-01-81
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

The Westinghouse P-250 computer was found stopped after a Rapid Access Disk (RAD) transmission error. Immediate efforts to restart the computer using bootstrap procedures were futile. Doors to the RAD and other cabinets were opened for troubleshooting purposes. After approximately ten minutes, the computer was bootstrapped successfully. It is suspected that seasonal high ambient room temperatures caused marginal RAD circuit operation resulting in the computer's inability to read or write stored data. No hardware nor software problems were detected.

In the summer season computer room temperature increases during periods of high outside air temperature. Room temperature reached approximately 85 degrees Fahrenheit on the date of the event. It is believed that this temperature affected the RAD operation. Since the fault symptom is intermittent, future action depends on the opportunity to troubleshoot the problem should the symptom return or a marginal circuit fail.