

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L J M F 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 6 0 5 0 0 0 3 6 4 7 0 8 0 6 8 1 3 0 9 0 4 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | At 1830 on 8/6/81 and 1245 on 8/18/81, the instrumentation loop associated with the

0 3 | Refueling Water Storage Tank (RWST) level transmitter (LT-501) was declared inoperable

0 4 | when the level indicator (LI-4075A) failed high. Tech. Spec. 3.3.3.8, in part, requires

0 5 | the instrumentation loop to be operable. Tech. Spec. 3.3.3.8 action statement require-

0 6 | ments were met. Health/safety of the public was not affected.

0 7 |

0 8 |

0 9 | I D 11 E 12 E 13 I N S T R U 14 T 15 Z 16

17 | 8 1 0 3 5 0 3 L 1

18 | E 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 W 1 2 0 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | These incidents were due to component drift in the level transmitter. Following the

1 1 | first occurrence, the level transmitter was recalibrated and returned to service at 0800

1 2 | on 8/8/81. Following the second occurrence, the D. C. Amplifier and calibration cards

1 3 | were replaced. No output drift has subsequently been noted. Following calibration, instru-

1 4 | mentation loop LT-501 was returned to service at 1300 on 8/20/81.

1 5 | E 29 9 9 N/A A 31 Operator Observation

1 6 | Z 33 Z 34 N/A N/A

1 7 | 0 0 0 Z 38 N/A

1 8 | 0 0 0 N/A

1 9 | Z 42 N/A

2 0 | N 44 N/A