

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 141 during performance of SP-158, Meteorological Monitoring Instrumentation

0 3 Calibration, it was discovered that the Control Room 175' wind speed recorder and

0 4 display was out of tolerance. This created an event contrary to T.S.3.3.3.4. Maintenance

0 5 was already in progress, and operability was restored at the time of discovery.

0 6 There was no effect upon the health or safety of the general public. This was the

0 7 fourth occurrence for the 175' wind speed indicator, and this is the fifteenth event

0 8 reported under this Specification.

0 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

SYSTEM CODE: I E 11 CAUSE CODE: X 12 CAUSE SUBCODE: Z 13 COMPONENT CODE: I N S T R U 14 COMP. SUBCODE: R 15 VALVE SUBCODE: Z 16

EVENT YEAR: 8 1 SEQUENTIAL REPORT NO.: 0 5 5 OCCURRENCE CODE: 0 3 REPORT TYPE: L REVISION NO.: 0

LER RO REPORT NUMBER: 17 ACTION TAKEN: E 18 FUTURE ACTION: Z 19 EFFECT ON PLANT: Z 20 SHUTDOWN METHOD: Z 21 HOURS: 0 0 0 0 ATTACHMENT SUBMITTED: Y 23 NPRD-4 FORM SUB.: N 24 PRIME COMP. SUPPLIER: A 25 COMPONENT MANUFACTURER: C 4 1 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event is attributed to instrument drift. The instrument was

1 1 recalibrated. No further corrective action is deemed necessary.

1 2

1 3

1 4

1 5 FACILITY STATUS: E 28 % POWER: 1 0 0 29 OTHER STATUS: N/A 30 METHOD OF DISCOVERY: B 31 DISCOVERY DESCRIPTION: Technician Observation 32

1 6 ACTIVITY CONTENT RELEASED OF RELEASE: Z 33 Z 34 AMOUNT OF ACTIVITY: N/A 35 LOCATION OF RELEASE: N/A 36

1 7 PERSONNEL EXPOSURES NUMBER: 0 0 0 37 TYPE: Z 38 DESCRIPTION: N/A 39

1 8 PERSONNEL INJURIES NUMBER: 0 0 0 40 DESCRIPTION: N/A 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42 DESCRIPTION: N/A 43

2 0 PUBLICITY ISSUED DESCRIPTION: N/A 45

8109110220 810904
PDR ADOCK 05000302
PDR

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

PHONE:

904/795-6486

SUPPLEMENTARY INFORMATION

REPORT: #50-302/81-055/03L-0

FACILITY: Crystal River Unit 3

REPORT DATE: September 4, 1981

Occurrence Date: August 7, 1981

IDENTIFICATION OF OCCURRENCE:

The meteorological monitoring system 175' wind speed recorder and display for the Control Room was out of tolerance contrary to Technical Specification 3.3.3.4.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 Power Operation (100%).

DESCRIPTION OF OCCURRENCE:

At 1415, during performance of SP-158, Meteorological Monitoring Instrumentation Calibration, it was discovered that the Control Room 175' wind speed recorder and display were out of tolerance. Maintenance was already in progress, and operability was restored at the time of discovery.

DESIGNATION OF APPARENT CAUSE:

The cause of this event is attributed to instrument drift.

ANALYSIS OF OCCURRENCE:

There was no effect upon the health or safety of the general public.

CORRECTIVE ACTION:

The instrument was recalibrated. No further corrective action is deemed necessary.

FAILURE DATA:

This is the fourth occurrence for the 175' wind speed indicator, and this is the fifteenth event reported under this Specification.