

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

REPORT
SOURCE

L 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0605 during normal operation, it was discovered that the Auxiliary Building

0 3 | Ventilation Exhaust System had no flow although fans AHF-14B & 14D were in operation.

0 4 | This created an event contrary to T.S.3.7.8.1. Fans 14A & 14C provided redundancy.

0 5 | Maintenance was initiated, and operability was restored at 1612. There was no effect

0 6 | upon the health or safety of the general public. This was the first occurrence of this

0 7 | type, and this is the fourteenth event reported under this Specification.

0 8 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 9 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 | LER/RO
REPORT
NUMBER | 8 1 | 21 22 | 23 | 24 25 26 | 27 | 28 29 | 30 | 31 | 32 | 33 34 | 35 | 36 | 37 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER

A 18 | Z 19 | Z 20 | Z 21 | 0 0 0 0 | Y 23 | N 24 | A 25 | J 0 9 0 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event is attributed to failure of solenoid JH351SV. The solenoid

1 1 | was replaced. No further corrective action is deemed necessary at this time.

1 2 |

1 3 |

1 4 |

1 5 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 6 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 7 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 8 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 9 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2 0 | 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARED

Victor A. Hernandez

PHONE

904/795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

8109110286 810904
PDR ADOCK 05000302
S PDR

NRC USE ONLY

SUPPLEMENTARY INFORMATION

REPORT: #50-302/81-053/03L-0

FACILITY: Crystal River Unit 3

REPORT DATE: September 4, 1981

Occurrence Date: August 5, 1981

IDENTIFICATION OF OCCURRENCE:

The Auxiliary Building ventilation exhaust system was inoperable contrary to Technical Specification 3.7.8.1.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 Power Operation (100%).

DESCRIPTION OF OCCURRENCE:

At 0605, during normal operation, it was discovered that the Auxiliary Building ventilation exhaust system had no flow although fans AHF-14B and 14D were in operation. Fan AHF-14A and 14C were started and flow returned to normal. Maintenance was initiated, and operability was restored at 1612.

DESIGNATION OF APPARENT CAUSE:

The cause of this event is attributed to failure of solenoid AH351SV, Johnson Service Company Model 49-21916.

ANALYSIS OF OCCURRENCE:

There was no effect upon the health or safety of the general public.

CORRECTIVE ACTION:

The solenoid was replaced. No further corrective action is deemed necessary at this time.

FAILURE DATA:

This was the first occurrence of this type, and this is the fourteenth event reported under this Specification.