

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M A P P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 58

CON'T
01 REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 0 7 1 3 8 1 8 0 9 0 3 8 1 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On July 13, 1981 during reactor startup, while conducting surveillance procedure
03 No. 8.7.1.7, the outer drywell personnel access door was discovered to have a leak
04 rate in excess of T.S. limits. The inner door seal had been proven to be intact.
05 The seal was replaced in-kind and a satisfactory leak rate test conducted at 1335
06 hrs. the same day. See Attachment
07
08
09

09 SYSTEM CODE S A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V E S S E L 14 COMP. SUBCODE G 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16
17 LER/RO REPORT NUMBER 8 1 21 22 SEQUENTIAL REPORT NO. 0 4 3 24 26 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 31 REVISION NO. 0 32
ACTION TAKEN A 18 G 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD 0 0 0 0 37 40 HOURS 22 ATTACHMENT SUBMITTED Y 23 NPSR-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 3 1 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the seal leakage has been determined to be normal in-service seal
11 degradation. A change to procedure 2.1.1, which requires a local leak rate test prior
12 to Reactor Coolant Temperature exceeding 212°F. has been made to preclude recurrence
13 of this event.
14

15 FACILITY STATUS X 28 % POWER 0 0 1 29 OTHER STATUS 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N.A. LOCATION OF RELEASE 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
20 PUBLICITY ISSUED N 44 DESCRIPTION 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8109150515 810903
PDR ADOCK 05000293
S PDR
NAME OF PREPARER G. G. Whitney

NRC USE ONLY
N.A.
68 69 80
PHONE: 617-746-7900

BOSTON EDISON COMPANY
PILGRIM NUCLEAR POWER STATION
DOCKET NO. 50-293

Attachment to LER 81-043/01T-0

On July 15, 1981, the Operations Review Committee (ORC) determined that degradation of the outer drywell access door seal was reportable per 10 CFR 50 Appendix J.

This determination was based on available information. However, the ORC requested the On-site Safety Group Leader to prepare a detailed report of the criteria for testing the drywell door seals. On August 19, 1981 the ORC reviewed this report and determined an immediate event report be issued since operating procedure 2.1.1 permitted (and operating personnel performed) a drywell entrance for a routine, scheduled inspection after reactor coolant temperature exceeded 212° F and before a satisfactory surveillance test of the drywell access door seals. To preclude a recurrence of this event, procedure 2.1.1 has been revised to require a local leak rate test of the door seals prior to a coolant temperature in excess of 212°F as well as after the required drywell inspection.