

LICENSEE EVENT REPORT

CONTROL BLOCK										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																																																															
N J S G S 1										0 0 - 0 0 0 0 0 - 0 0										4 1 1 1 1																																																																					
LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE										CAT 56																																																											
CON'T										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										PORT DATE																																																	
0 1										1 0 5 0 0 0 2 7 2 7										0 8 2 6 8 1										0 9 0 8 8 1																																																											
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES										On August 26, 1981, during a routine containment inspection, an operator discovered										service water leaking from the bottom secondary coil on No. 11 containment fan coil										unit (CFCU), at a rate of approximately 0.5 gallons per minute. In accordance with										NRC IE Bulletin 80-24, the NRC was notified of the service water leak in containment										by telephone, with written confirmation transmitted within the next 24 hours. No. 11										CFCU was removed from service, and declared inoperable. Action statement 3.6.2.3.b										was entered at 0125 hours, August 26, 1981, because No. 13 CFCU was also out of service.																			
SYSTEM CODE										CAUSE CODE										CAUSE SUBCODE										COMPONENT CODE										COMP SUBCODE										VALVE SUBCODE																																							
S B										E										B										H T E X C H										G										Z																																							
EVENT YEAR										SEQUENTIAL REPORT NO										OCCURRENCE CODE										REPORT TYPE										REVISION NO																																																	
8 1										0 7 4										0 1										T										0																																																	
ACTION TAKEN										FUTURE ACTION										EFFECT ON PLANT										SHUTDOWN METHOD										HOURS										ATTACHMENT SUBMITTED										NPRD-4 FORM SUB										PRIME COMP. SUPPLIER										COMPONENT MANUFACTURER									
F										A										Z										Z										0 0 0 0										Y										Y										Z										W 1 2 0									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS										The leakage was due to secondary coil failure. The leaking cooling coil was blank										flanged off and the CFCU was tested satisfactory and returned to service. Action										statement 3.6.2.3.b was terminated at 1853 hours, August 26, 1981.										(81-10, 81-11, 81-31, 81-39, 81-64, 81-72)																																																	
FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																																																	
E										0 9 6										N/A										B										Leak discovered during routine inspection.																																																	
ACTIVITY CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																																																																					
Z										N/A										N/A																																																																					
PERSONNEL EXPOSURES										PERSONNEL INJURIES										LOSS OF OR DAMAGE TO FACILITY										PUBLICITY																																																											
NUMBER										TYPE										DESCRIPTION										NUMBER										DESCRIPTION										TYPE										DESCRIPTION																													
0 0 0										Z										N/A										0 0 0										N/A										Z										N/A																													
ISSUED										DESCRIPTION										N/A										N/A										N/A										N/A																																							
2 0										N										N/A										N/A										N/A										N/A																																							

8109210184 810908
PDR ADOCK 05000272
S PDR

IRER Frank Dickey

PHONE 609-935-5100

609-935-5100