

LICENSER EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L J M F 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 5 0 5 0 0 0 3 6 4 7 0 8 1 2 8 1 3 0 9 1 0 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 1 2 At 1430 on 8/12/81, it was determined that the service water dilution flow recorder had
0 3 been inoperable since 8/7/81 due to a broken annubar. Tech. Spec. 3.3.3.10, in part,
0 4 requires the flow recorder to be operable. Tech. Spec. 3.3.3.10 action statement require-
0 5 ments were met. Health/safety of the public was not affected.
0 6
0 7
0 8

SYSTEM CODE M C 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE R 15 VALVE SUBCODE Z 16
 LEA/RO REPORT NUMBER 8 1 21 22 SEQUENTIAL REPORT NO. 0 3 6 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32
 ACTION TAKEN A 18 33 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 35 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED Y 22 41 NPRO-4 FORM SUB. N 24 42 PRIME COMP. SUPPLIER N 25 43 COMPONENT MANUFACTURER W 1 2 0 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 At the time the flow recorder was declared inoperable on 8/7/81, personnel involved in
1 1 issuing the Maintenance Work Request did not recognize this as a LCO Event. As a result,
1 2 the Tech. Spec. action statement requirement of estimating the discharge canal dilution
1 3 line flow rate every 4 hours was not met. However, an investigation revealed that adequate
1 4 dilution flow did exist for the 5 days from 8/7/81 to 8/12/81. Upon discovery of the

FACILITY STATUS E 28 8 9 % POWER 1 0 0 29 12 17 OTHER STATUS NA 30 44 METH. OF DISCOVERY A 31 45 46 DISCOVERY DESCRIPTION Operator Observation 32 48
 ACTIVITY CONTENT Z 33 39 44 RELEASED OF RELEASE Z 34 40 44 AMOUNT OF ACTIVITY NA 35 44 LOCATION OF RELEASE NA 36 45
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 40 TYPE Z 38 41 DESCRIPTION NA 39 44
 PERSONNEL INJURIES NUMBER 0 0 0 40 43 DESCRIPTION NA 41 44
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 45 DESCRIPTION NA 43 46

PUBLICITY ISSUED N 44 47 DESCRIPTION NA 45 48

8109220596 810910
 PDR ADOCK 05000364
 S PDR

NRC USE ONLY

NAME OF PREPARER: W. G. Hairston, III

PHONE: (205) 899-5156

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (cont'd)

condition, the action requirements were initiated and following necessary repairs and functional tests, the service water dilution flow recorder was returned to service at 1310 on 8/21/81. Personnel involved have been counseled concerning this event.